

Response to Office of Engineering and Technology E-mail Generated on 7/10/06
FCC File #: 0098-EX-RR-2006
Reference Number: 4457

The necessary bandwidth of 12.8 MHz is wider than the frequency ranges 476-482 MHz and 488-494 MHz. Please clarify this discrepancy.

The necessary bandwidth for the frequency ranges 476-482 MHz and 488-494 MHz should be 6 MHz.