

To: Ronald Quirk
E-Mail: req@commlawgroup.com
From: Doug Young
Date: October 14, 2016

Subject: Request for Info - File #0153-EX-CN-2016

Message:

All the emission designators for this application were entered incorrectly. It seems that the second character of the emission, the numeral "1," "7" or "9," was entered in the modulating signal field. This character should have been selected from the second dropdown list for emission. All emissions need to be corrected before processing can resume.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of October 14, 2016 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 34300