

To: Michael Miller
E-Mail: mlmiller@sterk.space
From: Leann Nguyen
Date: January 06, 2020

Subject: Request for Info - File # 0965-EX-CN-2019

Message:

Below is International Bureau requests, please send your response directly to Joseph Hill and Jeanette Spriggs and cc to me.

- The frequencies provided in the space cap do not match the frequencies provided in the form 442, please correct or provide justification as to why they are different.
- The space station and ground station antenna patterns indicate a beam width of 150 degrees, however the diagrams appear to show a beam width of approximately 130 degrees, applicant please verify the beam widths.
- Provide an interference analysis for the uplink/downlink.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of January 06, 2020 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 52642