

To: Daryl Hunter
E-Mail: daryl.hunter@viasat.com
From: Leann Nguyen
Date: March 30, 2009

Subject: FCC File# 0135-EX-ST-2009

Message:

Please submit the Stop Buzzer, who can terminate the system if having the interference, including name and phone number.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of March 30, 2009 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://gulfoss2.fcc.gov/prod/oet/cf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 8220