

To: Daryl Hunter
E-Mail: daryl.hunter@viasat.com
From: Leann Nguyen
Date: September 27, 2016

Subject: Request for Info - File # 1404-EX-ST-2016

Message:

Please verify the emission designator information. The bandwidth is incorrect.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of September 27, 2016 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 34093