

Technical Description

The Boeing Company

Submitted: 11/21/2012
Joel D. Thorsheim
The Boeing Company
Frequency Management Services MC: 2T-22
P.O. Box 3707
Seattle, WA 98124-2207
206-544-6066

The purpose of this modification request is to request the removal of Special Condition Number 8 on FCC call sign WE2XWG file number 0315-EX-RR-2012.

The FAA has allowed the removal of the Top Hat array limitation per attached FAA e-mail.

No technical data is changed under this modification.