

From: Chuck Zappala

To: John Kennedy

Date: January 14, 2005

Subject:

FCC File # 0239-EX-PL-2004

Message:

01/14/05

The emission designator in the Technical Description document is in error. The Application is correct. The emission designator should be as stated in the application as 2M10G7D. The roof mounted receive antenna is a GPS Networking Inc. model L1GPSA-N and has a filter that limits the re-rad to 2.1 MHz.

Thank you,

Chuck Zappala
FCC Licensing Specialist
The Boeing Company
Frequency Management Services
South Park Complex Bldg 15-01.1
Seattle, WA
P.O. Box 3707 MC: 2T-22
Seattle, WA 98124-2207
206-544-6580 Office
206-544-6592 Fax
866-248-1493 Toll Free