

To: Michael Miller
E-Mail: mlmiller@sterk.space
From: Nimesh Sangani
Date: February 04, 2021

Subject: Additional Information Request

Message:

There is no GIMS file or antenna reference pattern identified in the spacecap. There appears to be attachments indicated but no attachments can be seen. Please ask the applicant to provide the GIMS mdb file or identify the antenna reference pattern in the spacecap file.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of February 04, 2021 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 59818