


W22 System Diagram



PARTS LIST

Ref Des	Part Number	Description	Manufacturer
E1	L1A-PM-N(f)	Active Antenna	GPS Source
W1	LMR-400	Coax Cable	Andrew
A1	GPSRKXLV-P110/5-NF	Power Controller	GPS Source
E2	L1P	Passive Antenna	GPS Source