

Prior License Rejection

A previous license filed under the file number **0283-EX-PL-2010** was rejected because the geographical coordinates of the ground station antenna were incorrect and it seemed the ground station was in water. For this new application, the correct coordinates have been provided.