

To: David Barnes
E-Mail: Howard.Jetmundsen@echostar.com
From: Anthony Serafini
Date: May 19, 2005

Subject:

Message:

Please provide a "stop buzzer" contact that will be responsible for testing and can stop the testing in case of interference.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of May 19, 2005 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at https://gulfoss2.fcc.gov/prod/oet/index_els.html by clicking on the "Submit Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 3657