

From: John Benson

To: Leann Nguyen

Date: October 21, 2016

Subject: Request for Info - File # 0146-EX-CN-2016

Message:

A "Stop Buzzer" point of contact for the authorized device must be identified and available at all times during GPS re-radiation operation of the device under any condition.

Karl Benson
office: 503-498-3978
cell: 503-878-3422