

From: Brian Miller

To: Doug Young

Date: March 06, 2017

Subject: Request for Info - File #0073-EX-CM-2017

---

Message:

The reason for the modification is due to the fact I made a mistake and listed 50kHz as the bandwidth for all bands, which is incorrect. The 909.75-921.75MHz bands should be 5MHz for the bandwidth. Any additional questions please let me know.