

From: oeotech@fccsun27w.fcc.gov
To: [Hung Le](#)
Subject: Coordination Request Complete for File Number: 0722-EX-CN-2019
Date: Saturday, October 12, 2019 3:36:15 AM


[FCC Home](#) | [Search](#) | [RSS](#) | [Updates](#) | [E-Filing](#) | [Initiatives](#) | [Consumers](#) | [Find People](#)



Office of Engineering and Technology

All coordination requests for file number 0722-EX-CN-2019 have been given final status by OFACS. The FAS charge for this filing has now been closed.

Coordination Results:

NG Number	Status Code	Status Description	Condition Code	SCB Comments
NG 232964	66	Coordination Complete	2	N/A

Agreement Text:

NG Number	Notes	Agreement Text
NG 232964	Per clearance - GPS re-radiators must operate in accordance with Section 8.3.28 of the NTIA Manual.power spectral density of the signal should be very well controlled behind the building.;	\$\$ADD NG 232964 TYP01 N SEC01 07233 RVS01 07233 SER01 NG 232964 CLA01 U FRQ01 M1575.420000 NET01 ELS10 IPD01 190924 DEC01 ACCEPT BUR01 FCC EXD01 211120 STC01 XT EMS01 20M00D7D PWR01 W0.00001 NTS01 S406 XSC01 NH XAL01 NASHUA XRC01 20192399 XLA01 424525N XLG01 0712923W XCL01 WK 2XMP RSC01 NH RAL01 NASHUA RLA01 424525N RLG01 0712923W REM01 *AGN,GEOPHYSICAL SURVEY SYSTEMS, INC. REM02 *AGN,PWR IS ERP REM03 *FLN,0722-EX-CN-2019 SUP01 EXPERIMENTAL RNSS TEST EQUIPMENT FOR THE PURPOSE OF TESTING GPS SUP02 RECEIVER. STOP BUZZER IS

MANUFACTURING GPS REPEATER 603-893-1109

ACL01 WK 2XMP

DAT01 190920

LBO DATE: 09/20/2019

IRAC COMMENTS: APPROVED NTIA 10-10-2019

DATA CHANGES: FCC=>NTIA CHANGES ARE

EXD01:250106=>211120; NTS01:_=>S406;

SCB COMMENTS: Per clearance - GPS re-radiators must operate in accordance with Section 8.3.28 of the NTIA Manual.power spectral density of the signal should be very well controlled behind the building.; \$

IDKT: J1543600