

To: CAROLANN SCHMITT
E-Mail: moysenka@tycoelectronics.com
From: Behnam Ghaffari
Date: May 05, 2009

Subject: FCC File No. 0035-EX-ML-2009

Message:

Ms. Schmitt,

The coordinates for antenna 4 (Lat: 40-18-49 N and Long: 76-47-12 W), do not match with the address shown on the application ("1 EXECUTIVE PARK DRIVE, SUITE 205, Albany, NY"). Please correct either the coordinates or the address.

Please provide a 24x7 point of contact to cease operation if interference occurs.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of May 05, 2009 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://gulfoss2.fcc.gov/prod/oet/cf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 8496