

To: Arnal Cook
E-Mail: ACook@oh.hra.com
From: Doug Young
Date: August 20, 2013

Subject: Request for Info - File #0341-EX-PL-2013

Message:

1. Your application requires coordination of the bands and spot frequencies 1134.4-1164.45, 1188.45-1215.6, 1239.6, 1240-1300, 1337.9-1350, 1350-1367.913 and 2900-3100 MHz with an FAA Regional Frequency Management Office using the procedures below.

The Federal Aviation Administration (FAA) Great Lakes Regional Frequency Management Office should be contacted at:

Federal Aviation Administration Frequency
Management Officer
AGL-474
O'Hare Lake Office Center
2300 East Devon Avenue
Des Plaines, Illinois 60018
Telephone: (847) 294-8443 Fax: (847) 294-7133

Please report the following information to the FAA Regional Frequency Management Office. (Ensure that the information indicated by the asterisks (*) is reported for the frequencies 1188.45-1215.6, 1239.6, 1240-1300, 1337.9-1350, 1350-1367.913 and 2900-3100 MHz.) Write "None" for a parameter if it is considered not applicable to the experiment:

- *peak envelope power (PEP);
- type of antenna;
- transmit antenna gain;
- elevation above sea level of the antenna site;
- height above ground of the focal point of the antenna;
- antenna polarization;
- the azimuth that the antenna is pointed or appropriate designator to indicate whether the antenna is rotating, non-directional, etc.;
- *pulse repetition rate (PRR) that the equipment is capable of operating on to include PRR stagger sequences if appropriate, whether the PRR is adjustable and what PRR's the equipment can accept, and any other information that would be helpful in understanding the pulse characteristics of the equipment;
- *pulse width;
- equipment nomenclatures;
- *whether the equipment is capable of blanking transmissions in certain azimuths and any limitations with respect to blanking;
- radius of operations if appropriate;
- detailed description of the proposed operation to include any technical parameters that will be altered during operations.

Report back to this office when coordination with the regional offices has been completed, and report any "NGT" numbers assigned by the regional offices. If any of the bands listed above can be notched out, then FAA Regional coordination will not be necessary.

2. The use of 1435-1525 MHz and 2310-2390 MHz requires pre-coordination with

Aerospace and Flight Test Radio Coordinating Council (AFTRCC)
P.O. Box 200547
Cartersville, GA 30120-9010
Coordination point contact: Mr. Darryl J. Holtmeyer, Telephone: (314) 233-1117.

Submit successful coordination with AFTRCC as a response to this correspondence.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of August 20, 2013 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://gulfoss2.fcc.gov/prod/oet/cf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 21274