

To: Maximilian Moy
E-Mail: max.moy@lmco.com
From: Behnam Ghaffari
Date: June 11, 2015

Subject: FCC File No. 0334-EX-PL-2015

Message:

Need further information regarding the actual transmitter output power and antenna information (e.g., gain, orientation/radiation pattern).

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of June 11, 2015 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 28363

To: Maximilian Moy
E-Mail: max.moy@lmco.com
From: Behnam Ghaffari
Date: June 11, 2015

Subject: FCC File No. 0334-EX-PL-2015

Message:

Need further information regarding the actual transmitter output power and antenna information (e.g., gain, orientation/radiation pattern).

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of June 11, 2015 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 28364