

To: Victor Tang
E-Mail: vtang@metlabs.com
From: Behnam Ghaffari
Date: October 17, 2012

Subject: FCC File No. 0808-EX-ST-2012

Message:

First, you will need to lower the ERP; this (19.28 W) ERP is too high for EMC testing (~1 W). Second, the requested freq bands need to be carved out of aeronautical and public safety bands. Third, the bandwidth of 920 MHz needs to be adjusted appropriately. Forth, the testing will have to be conducted in an enclosed area or building.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of October 17, 2012 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 18329