

**TECHNICAL STATEMENT
CONCERNING PROPOSED MEDIAFLO
OPERATIONS**

TEMPORARY STATIONS IN DENVER MARKET

Summary of MediaFLO facilities for this market:

- Denver, CO, DNTOW1, 39-44-40, 104-59-43, Rc=1592 m AMSL, 22.5 kW-ND
- Denver, CO, DNTOW2, 39-44-50, 105-00-24, Rc=1583 m AMSL, 22.5 kW-ND

Note: There are no full-service TV or DTV stations affected by this proposal. See Figure 1.

TV Inquiry

du Treil, Lundin, & Rackley, Inc., Sarasota, Florida



Listed stations are within 1000 km of the point at 039-44-40.00 104-59-43.00.

Callsign	Status	Channel	Offset	Service	City	State	Latitude	Longitude	Application ID	Distance (km)		
ARN		DA	Antenna ID	Rotation	ERP (kW)	HAAT (m)	RCAMSL (m)	Zone	Record Type	Facility ID	Bearing (deg)	
KOTV	LIC	55		DT	TULSA		OK	036-01-15	095-40-32	1077721	918.17	
BLCDDT	20050525AFX	D	28320		0	970	490.4	684.8	2	C	35434	113.93
KJRH	LIC	56		DT	TULSA		OK	036-01-15	095-40-32	594113	918.17	
BLCDDT	20020208AAV	N	28505			800	505	698	2	C	59439	113.93
KNXV-TV	LIC	56		DT	PHOENIX		AZ	033-20-00	112-03-46	432165	952.19	
BLCDDT	20000120AAR	N	31257			73	509	866	2	C	59440	223.69
KNXV-TV	CP MOD	56		DT	PHOENIX		AZ	033-20-00	112-03-46	431293	952.19	
BMPDDT	19991230ABB	N	30896			500	509	865.6	2	C	59440	223.69
KDMI	LIC	56		DT	DES MOINES		IA	041-49-47	093-36-56	1142672	988.05	
BLCDDT	20060825ACT	D	75868		270	1000	589	881.6	2	C	78915	72.71

There are no full-service TV or DTV stations on Channel 55 located within 429 km of the Denver market. There are no full-service TV or DTV stations on Channels 54 or 56 located within 229 km of the Denver market. The closest full-service TV or DTV station on Channels 54, 55 or 56 is located more than 918 km distant from the Denver market. Therefore, there is no interference potential from the proposed facilities.