

Reason for Modification of FCC License WL2XMV:

Raytheon Company ("Raytheon") proposes to modify license WL2XMV to permit a market trial of its Skyler radar and to make certain changes to technical specifications of the license.

Data to be Modified:

- Antenna boresight must be set between 70 – 80 degrees.
- Antenna azimuth between 20 and 130 degrees.
- Antenna Height: 85 feet

Location Affected:

- City: Oxford, FL
- Lat/Long: NL 28-55-09; WL 82-02-06

Frequencies Affected:

- 9010 MHz and 9190 MHz
- Station Class: Fixed

FAA Coordination was submitted on September 14, 2021.

- Tracking Numbers: TRK 210812 and TRK 210813

Stop Buzzer:

Michael Dubois

Email: michael.dubois@raytheon.com

W: (508)490-1707

M: (508)353-6317