

To: Glenn Hall
E-Mail: glenn.hall@saabsensis.com
From: Doug Young
Date: June 05, 2015

Subject: Request for Info - STA File #0600-EX-ST-2015

Message:

The original transmitter location lists the power in ERP while the recently added ones do not. We prefer power values in ERP whenever possible.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of June 05, 2015 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 28321