

To: Brian Weimer
E-Mail: bweimer@sheppardmullin.com
From: Doug Young
Date: May 01, 2014

Subject: Request for Info - STA File #0291-EX-ST-2014

Message:

There is potential interference on 13.49 MHz and 162.7 MHz. Can you use replacement frequencies, and do you have any to suggest?

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of May 01, 2014 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 23750