

From: Ron Center

To: Leann Nguyen
Date: April 15, 2008

Subject: FCC File# 0186-Ex-ST-2008

Message:

In response to your inquiry, this test is required to be conducted outside, which eliminates any issues with reflections and intermodulation interference.

Sincerely,
Ron Center
The Boeing Company
Frequency Management Services
Seattle, WA
(206) 544-6583