

From: daniel.r.orear@faa.gov
To: Thorsheim_Joel_D
Cc: victor.hinton@faa.gov; Thomas.CTR.Christein@faa.gov
Subject: Re: FW: FCC File# 0207-EX-RR-2012
Date: Monday, June 25, 2012 7:55:38 AM
Attachments: [WC2XKB_0133-EX-ML-2011.pdf](#)

Renewal authorized for experimental testing at the four locations below IAW the specifications and procedures stated below and in the attached.

Location	Frequency	FAA Coordination #
Everett, WA	M116.45	NG T120249
Seattle, WA	M116.35	NG T120250
Moses Lake, WA	M112.85	NG T120251
Glasgow, MT	M115.35	NG T120252

Dan ORear
ATO Western Service Area
Northwest Mountain Region
Spectrum Engineering Services
425-227-2637

From: "Thorsheim, Joel D" <Joel.D.Thorsheim@boeing.com>
To: Daniel R ORear/ANM/FAA@FAA
Date: 06/22/2012 08:31 AM
Subject: FW: FCC File# 0207-EX-RR-2012

Dan,

We are submitting an application for renewal of experimental license WC2XKB (attached). This license supports aircraft noise testing certification. Below are the NG T numbers previously used.

Location	Frequency	FAA Coordination #
Everett, WA	M116.45	NG T100261
Seattle, WA	M116.35	NG T100260
Moses Lake, WA	M112.85	NG T100262
Glasgow, MT	M115.35	NG T100263

If you have any questions please let us know.

Thanks


Joe

Joe Thorsheim
Frequency Management Services, M/C 2T-22
The Boeing Company
Phone: (206) 544-6066
Fax: (206) 662-0701

From: oetech@fccsun27w.fcc.gov [<mailto:oetech@fccsun27w.fcc.gov>]
Sent: Friday, June 22, 2012 6:53 AM
To: GRP FMS FCC Correspondence
Subject: FCC File# 0207-EX-RR-2012



[FCC Home](#) | [Search](#) | [RSS](#) | [Updates](#) | [E-Filing](#) | [Initiatives](#) | [Consumers](#) | [Find People](#)



Office of Engineering and Technology

To: Ronald Center, THE BOEING COMPANY
fmsfcccorrespondence@boeing.com

From: Leann Nguyen
Leann.Nguyen@fcc.gov

Applicant: THE BOEING COMPANY
File Number: 0207-EX-RR-2012
Correspondence Reference Number: 17286
Date of Original Email: 06/22/2012

Mr. Center, Please submit FAA coordination including NG T numbers and FAA Point-of-contact.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of 06/22/2012 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the reply button. In order for your response to be processed expeditiously, you must upload your response via the Internet by visiting [The OET Experimental Licensing System](#), followed by clicking on the "Reply to Correspondence" hyperlink.