

To: Michael Viau
E-Mail: fmsfcccorrespondence@boeing.com
From: Leann Nguyen
Date: April 22, 2015

Subject: FCC File 0251-EX-ST-2015

Message:

Please submit the following information

1. Explain why it is necessary to have a frequency in the 1240-1350 MHz range for a direction finder.
2. User must describe antenna type and its gain.
3. Why the requirement for a 5 kilometer radius?

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of April 22, 2015 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 27666