

From: daniel.r.orear@faa.gov
To: [Thorsheim, Joel D](#)
Cc: Thomas.Ahn@faa.gov
Subject: Re: FAA Coordination Request for WF2XDT Renewal
Date: Tuesday, August 27, 2013 8:01:05 AM
Attachments: [WF2XDT_0308-EX-RR-2011.pdf](#)

Concur with the renewal of the 1090 MHz TCAS testing as specified in the attached. FAA coordination # NG T130305.

Dan ORear
ATO Western Service Area
Northwest Mountain Region
Spectrum Engineering Services
425-227-2637

From: "Thorsheim, Joel D" <Joel.D.Thorsheim@boeing.com>
To: Daniel R ORear/ANM/FAA@FAA
Date: 08/26/2013 10:43 AM
Subject: FAA Coordination Request for WF2XDT Renewal

Hi Dan,

The attached TCAS license is coming up for renewal again. Can we obtain new FAA coordination for the renewal?

Let me know if you have any questions.

Thanks

Joe

Joe Thorsheim
Frequency Management Services, M/C 2T-22
The Boeing Company
Phone: (206) 544-6066
Fax: (206) 662-0701

From: daniel.r.orear@faa.gov [<mailto:daniel.r.orear@faa.gov>]
Sent: Tuesday, September 13, 2011 7:13 AM
To: Thorsheim, Joel D
Subject: Re: FW: OET Experimental License Expiration Notification, Call Sign: WF2XDT