




AEROSPACE & FLIGHT TEST RADIO COORDINATING COUNCIL®

POST OFFICE BOX 200547, CARTERSVILLE, GA 30120-9010

TELEPHONE (770) 494-2893

TELEMETRY FREQUENCY RECOMMENDATION

February 21, 2007

Identity Control No: 1144-07

Bertin Koala Tel: 206-544-5697, Email: bertin.koala@boeing.com
The Boeing Company
P.O. Box 3707, MC 2T-22
Seattle, WA 98124-2207

AFTRCC recommends a new 2 year Experimental FCC License for the operation of an outdoor antenna range supporting the testing of antennas for aerospace programs, detailed as follows:

TRANSMITTER

MAKE / MODEL

Multiple

STABILITY

0.003% or better

RF Spectrum Parameters:

<i>Band Assignment:</i>	1435 to 1525 MHz
<i>Emission Designator:</i>	NON
<i>Output Power:</i>	5 Watts ERP
<i>Maximum Altitude</i>	Ground Operation Only
<i>Max. Antenna Height Above Ground:</i>	30 Feet

DATES OF OPERATION: [March 1, 2007 through March 1, 2009](#)

AREAS OF OPERATION: [10 MIRAD \(16 kmRAD \)](#) of the following:

<u>AREA</u>	<u>LATITUDE</u>	<u>LONGITUDE</u>
Mesa, AZ	33-28-07N	111-43-40W (NAD 83)

This recommendation has been coordinated with the following:


DOD Area Frequency Coordinator, Kenneth Wong, Email: kenneth.wong@hua.army.mil
Tel: 520-538-6424

We request that the FCC add the following to your license:

[“Renewal of this License is subject to prior coordination with AFTRCC Frequency Advisory Committee, PO Box 200547, Cartersville, GA 30120-9010, Telephone \(770\) 494-2893.”](#)

This recommendation is advisory only and not binding on the applicant or the FCC. This does not constitute a judgment that a frequency is best suited to the applicant's purpose nor that the assignment is exclusive to the applicant. In utilizing this recommendation, the applicant agrees to release and hold harmless AFTRCC, its officers, directors, members, agents and representatives in any claims, losses or expenses which may arise as a result of the applicant's use of these frequencies.

This recommendation will be valid for 90 days from the date of this letter. An updated letter should be requested if your license application has not been filed with the FCC within the 90-day period.

A handwritten signature in black ink, reading "Darryl J. Holtmeyer". The signature is fluid and cursive, with a long horizontal stroke at the end.

Darryl J. Holtmeyer, AFTRCC Non-Government Frequency Coordinator
AFTRCC Frequency Advisory Committee
Tel: 314-233-1117 Fax: 425-965-8233
Email: darryl.j.holtmeyer@boeing.com

Enclosure