Radisys Corporation 8900 NE Walker Road, Suite# 130, Hillsboro, Oregon, United States 97006 Tel.no.: 224-221-1417

Date: February 20, 2024

FCC Laboratory 7435 Oakland Mills Rd Columbia MD 21046

To whom it may concern,

This Change of Identification request applies for a new FCC ID as established in 47 CFR §2.933 for a currently approved device. This application by Radisys Corporation will establish a new FCC ID: 2A29YS4844L-A under Radisys Corporation grantee code for the purpose of marketing. The original grant to LIONS Taiwan Technology Inc. will remain in effect.

Per 2.933(b)

- 1. The original identification is 2AZULRS8682.
- 2. The original grant date is 01/15/2024.
- 3. The equipment is electrically identical. Only the trade name, model, and FCC ID number are different.
- 4. The original test results continue to be representative of and applicable to the equipment bearing the changed identification.
- 5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

- Cover Letter
- External Photos
- FCC ID label format and location

Should there be any question, please feel free to contact us.

Sincerely yours,

Mahman.

Md Rahman md.rahman@radisys.com