

Radisys Corporation
8900 NE Walker Road, Suite# 130, Hillsboro, Oregon, United States 97006
Tel.no.: 224-221-1417

Date: March 23, 2024

FCC Laboratory
7435 Oakland Mills Rd
Columbia MD 21046

To whom it may concern,

This Change of Identification request applies for a new FCC ID as established in 47 CFR §2.933 for a currently approved device. This application by Radisys Corporation will establish a new FCC ID: 2A29YS4844L-D under Radisys Corporation grantee code for the purpose of marketing. The original grant to LIONS Taiwan Technology Inc. will remain in effect.

Per 2.933(b)

1. The original identification is **2AZULRS8682**.
2. The original grant date is **03/19/2024**.
3. The equipment is electrically identical. Only the trade name, model, and FCC ID number are different.
4. The original test results continue to be representative of and applicable to the equipment bearing the changed identification.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

- ♦ Cover Letter
- ♦ External Photos
- ♦ FCC ID label format and location

Should there be any question, please feel free to contact us.

Sincerely yours,



Md Rahman
md.rahman@radisys.com