



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:16:14

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:16:25

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:16:42

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:16:52

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:17:13

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:17:23

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:17:43

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:17:54

### Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:18:14

### Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:18:24

### Band 2\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:18:44

### Band 2\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:18:55

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:19:15

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:19:25

### Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 16:19:45


### Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 23.AUG.2021 16:19:56




### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:20:13

### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:20:24

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:20:49

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:20:59

### Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:21:22

### Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:21:32

### Band 2\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:21:51

### Band 2\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:22:02

### Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:22:29

### Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:22:39

### Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:23:03

### Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:23:14

### Band 2\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:23:37

### Band 2\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:23:48

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 16:24:15


### Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 23.AUG.2021 16:24:25




### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:24:49

### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:25:00

### Band 2\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:25:23

### Band 2\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:25:34

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:25:54

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:26:04

### Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:26:24

### Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:26:35

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:26:55

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:27:05

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:27:25

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:27:36

### Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:27:55

### Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:28:06

### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 16:28:23


### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 23.AUG.2021 16:28:33




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:28:53

### Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:29:04

### Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:29:21

### Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:29:31

### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:29:48

### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:29:59

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:30:24

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:30:34

### Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:30:53

### Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:31:04

### Band 4\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:31:23

### Band 4\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:31:34

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:32:00

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:32:10

### Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 16:32:34


### Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)



Date: 23.AUG.2021 16:32:45




### Band 4\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:33:08

### Band 4\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:33:19

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:33:45

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:33:55

### Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:34:19

### Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:34:29

### Band 4\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:34:53

### Band 4\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:35:04

### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:35:23

### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:35:34

### Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:35:51

### Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:36:01

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:36:25

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:36:36

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 16:36:58


### Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 23.AUG.2021 16:37:09




### Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:37:29

### Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:37:40

### Band 5\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:37:56

### Band 5\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:38:07

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:38:27

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:38:38

### Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:38:55

### Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:39:05

### Band 5\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:39:22

### Band 5\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:39:33

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:39:58

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:40:09

### Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:40:28

### Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:40:42

### Band 5\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 16:41:01


### Band 5\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 23.AUG.2021 16:41:11




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:41:32

### Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 23.AUG.2021 16:41:42

### Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:41:59

### Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 23.AUG.2021 16:42:10

### Band 7\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:42:27

### Band 7\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 23.AUG.2021 16:42:37

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:43:00

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 23.AUG.2021 16:43:10

### Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:43:29

### Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 23.AUG.2021 16:43:40

### Band 7\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:43:59

### Band 7\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 23.AUG.2021 16:44:10

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:44:36

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 23.AUG.2021 16:44:47

### Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 16:45:11


### Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)



Date: 23.AUG.2021 16:45:21




### Band 7\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:45:45

### Band 7\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 23.AUG.2021 16:45:55

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:46:23

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 23.AUG.2021 16:46:33

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:47:00

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 23.AUG.2021 16:47:14

### Band 7\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:47:40

### Band 7\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 23.AUG.2021 16:47:51

### Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:48:14

### Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:48:25

### Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:48:44

### Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:48:55

### Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:49:16

### Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:49:29

### Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 16:49:49


### Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 23.AUG.2021 16:49:59




### Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 16:50:16


### Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 23.AUG.2021 16:50:27




### Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:51:17

### Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:52:06

### Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:52:57

### Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:53:11

### Band 12\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 16:53:27


### Band 12\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)



Date: 23.AUG.2021 16:53:48




### Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:54:42

### Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:54:53

### Band 12\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 16:55:15


### Band 12\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 23.AUG.2021 16:55:25




### Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 16:55:48


### Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)



Date: 23.AUG.2021 16:55:59




### Band 17\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:56:46

### Band 17\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:56:57

### Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:57:22

### Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:57:32

### Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:57:52

### Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:58:02

### Band 17\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:58:21

### Band 17\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 23.AUG.2021 16:58:32

### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:58:55

### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 16:59:05

### Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 16:59:22


### Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)



Date: 23.AUG.2021 16:59:33




### Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 16:59:53

### Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:00:03

### Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 17:00:26

### Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:00:37

### Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 17:00:54

### Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:01:04

### Band 66\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 17:01:21

### Band 66\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:01:35

### Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 17:01:58

### Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:02:08

### Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 17:02:29

### Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:02:39

### Band 66\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 17:02:56

### Band 66\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:03:07

### Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 17:03:29


### Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)



Date: 23.AUG.2021 17:03:40




### Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 17:03:59

### Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:04:09

### Band 66\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 17:04:29

### Band 66\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:04:39

### Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 17:05:09

### Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:05:20

### Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 17:05:43

### Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:05:54

### Band 66\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 17:06:17

### Band 66\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:06:28

### Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 17:06:54

### Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:07:05

### Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 23.AUG.2021 17:07:32

### Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 23.AUG.2021 17:07:42

### Band 66\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 23.AUG.2021 17:08:06


### Band 66\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 23.AUG.2021 17:08:16




### Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 24.AUG.2021 16:15:45

### Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 24.AUG.2021 16:15:56

### Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 24.AUG.2021 16:16:13

### Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 24.AUG.2021 16:16:23

### Band 41\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 24.AUG.2021 16:16:40

### Band 41\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 24.AUG.2021 16:16:51

### Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.AUG.2021 16:17:12

### Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 24.AUG.2021 16:17:23

### Band 41\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.AUG.2021 16:17:45

### Band 41\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 24.AUG.2021 16:17:55

### Band 41\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 24.AUG.2021 16:18:14

### Band 41\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 24.AUG.2021 16:18:25

### Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 24.AUG.2021 16:18:50

### Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 24.AUG.2021 16:19:01

### Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 24.AUG.2021 16:19:27


### Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)



Date: 24.AUG.2021 16:19:38




### Band 41\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 24.AUG.2021 16:20:01

### Band 41\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 24.AUG.2021 16:20:12

### Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 24.AUG.2021 16:20:38

### Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 24.AUG.2021 16:20:48

### Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 24.AUG.2021 16:21:12

### Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 24.AUG.2021 16:21:22

### Band 41\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 24.AUG.2021 16:21:46

### Band 41\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)



Date: 24.AUG.2021 16:22:00