



Date: 28.OCT.2021 15:08:14

11AX20SISO Ant0_5320




Date: 28.OCT.2021 15:00:14

11A_Ant1_5180




Date: 28.OCT.2021 15:21:30

11A_Ant1_5200




Date: 28.OCT.2021 15:24:16

11A_Ant1_5240




Date: 28.OCT.2021 15:26:12

11A_Ant1_5260




Date: 28.OCT.2021 15:27:55

11A_Ant1_5280




Date: 28.OCT.2021 15:29:38

11A_Ant1_5320




Date: 28.OCT.2021 15:31:16

11N20MIMO_5180




Date: 28.OCT.2021 15:33:25

11N20MIMO_5200




Date: 28.OCT.2021 15:35:16

11N20MIMO_5240




Date: 28.OCT.2021 15:36:43

11N20MIMO_5260




Date: 28.OCT.2021 15:38:26

11N20MIMO_5280




Date: 28.OCT.2021 15:39:53

11N20MIMO_5320




Date: 28.OCT.2021 15:41:44

11N40MIMO_5190




Date: 28.OCT.2021 15:43:36

11N40MIMO_5230




Date: 28.OCT.2021 15:45:25

11N40MIMO_5270




Date: 28.OCT.2021 15:47:15

11N40MIMO_5310




Date: 28.OCT.2021 15:50:30

11AC20MIMO_5180




Date: 28.OCT.2021 15:54:36

11AC20MIMO_5200




Date: 28.OCT.2021 15:56:31

11AC20MIMO_5240




Date: 28.OCT.2021 15:57:59

11AC20MIMO_5260




Date: 28.OCT.2021 15:59:29

11AC20MIMO_5280




Date: 28.OCT.2021 16:01:00

11AC20MIMO_5320




Date: 28.OCT.2021 16:02:39

11AC40MIMO_5190




Date: 28.OCT.2021 16:04:39

11AC40MIMO_5230




Date: 28.OCT.2021 16:06:22

11AC40MIMO_5270




Date: 28.OCT.2021 16:08:05

11AC40MIMO_5310




Date: 28.OCT.2021 16:09:36

11AC80MIMO_5210




Date: 28.OCT.2021 16:11:38

11AC80MIMO_5290




Date: 28.OCT.2021 16:13:31

11AX20MIMO_5180




Date: 28.OCT.2021 16:15:30

11AX40MIMO_5190




Date: 28.OCT.2021 16:27:52

11AX20MIMO_5200




Date: 28.OCT.2021 16:17:58

11AX80MIMO_5210




Date: 28.OCT.2021 16:35:22

11AX40MIMO_5230




Date: 28.OCT.2021 16:29:35

11AX20MIMO_5240




Date: 28.OCT.2021 16:21:05

11AX20MIMO_5260




Date: 28.OCT.2021 16:22:43

11AX40MIMO_5270




Date: 28.OCT.2021 16:31:34

11AX20MIMO_5280




Date: 28.OCT.2021 16:24:23

11AX80MIMO_5290




Date: 28.OCT.2021 16:37:14

11AX40MIMO_5310





Date: 28.OCT.2021 16:33:17

11AX20MIMO_5320




Date: 28.OCT.2021 16:26:01

ETH2:




11A_Ant0_5240




Date: 27.OCT.2021 12:13:32

11A_Ant0_5260




Date: 27.OCT.2021 12:15:26

11A_Ant0_5280




Date: 27.OCT.2021 12:17:08

11A_Ant0_5320




Date: 27.OCT.2021 12:18:44

11A_Ant0_5500




Date: 27.OCT.2021 12:20:31

11A_Ant0_5580




Date: 27.OCT.2021 12:22:20

11A_Ant0_5700




Date: 27.OCT.2021 12:27:57

11A_Ant0_5720_UNII-2C




Date: 27.OCT.2021 12:31:29

11A_Ant0_5720_UNII-3




Date: 27.OCT.2021 12:31:35

11A_Ant0_5745




Date: 27.OCT.2021 12:34:14

11A_Ant0_5785




Date: 27.OCT.2021 12:37:01

11A_Ant0_5825




Date: 27.OCT.2021 12:39:01

11N20SISO_Ant0_5180




Date: 27.OCT.2021 12:41:26

11N20SISO_Ant0_5200




Date: 27.OCT.2021 12:42:53

11N20SISO_Ant0_5240




Date: 27.OCT.2021 12:44:26

11N20SISO_Ant0_5260




Date: 27.OCT.2021 12:46:10

11N20SISO_Ant0_5280




Date: 27.OCT.2021 12:47:49

11N20SISO_Ant0_5320




Date: 27.OCT.2021 12:49:37

11N20SISO_Ant0_5500




Date: 27.OCT.2021 12:52:41

11N20SISO_Ant0_5580




Date: 27.OCT.2021 12:54:18

11N20SISO_Ant0_5700




Date: 27.OCT.2021 12:56:18

11N20SISO_Ant0_5720_UNII-2C




Date: 27.OCT.2021 12:58:07

11N20SISO_Ant0_5720_UNII-3




Date: 27.OCT.2021 12:58:13

11N20SISO_Ant0_5745




Date: 27.OCT.2021 13:00:04

11N20SISO_Ant0_5785




Date: 27.OCT.2021 14:36:01

11N20SISO_Ant0_5825




Date: 27.OCT.2021 14:37:55

11N40SISO_Ant0_5190




Date: 27.OCT.2021 14:40:05

11N40SISO_Ant0_5230




Date: 27.OCT.2021 14:41:59

11N40SISO_Ant0_5270




Date: 27.OCT.2021 14:43:52

11N40SISO_Ant0_5310




Date: 27.OCT.2021 14:45:55

11N40SISO_Ant0_5510




Date: 27.OCT.2021 14:47:39

11N40SISO_Ant0_5550




Date: 27.OCT.2021 14:50:08

11N40SISO_Ant0_5670




Date: 27.OCT.2021 14:52:35

11N40SISO_Ant0_5710_UNII-2C




Date: 27.OCT.2021 14:54:28

11N40SISO_Ant0_5710_UNII-3




Date: 27.OCT.2021 14:54:34

11N40SISO_Ant0_5755




Date: 27.OCT.2021 14:56:36

11N40SISO_Ant0_5795




Date: 27.OCT.2021 14:58:34

11AC20SISO_Ant0_5180




Date: 27.OCT.2021 15:00:12

11AC20SISO_Ant0_5200




Date: 27.OCT.2021 15:01:58

11AC20SISO_Ant0_5240




Date: 27.OCT.2021 15:03:27

11AC20SISO_Ant0_5260




Date: 27.OCT.2021 15:05:14

11AC20SISO_Ant0_5280




Date: 27.OCT.2021 15:06:48

11AC20SISO_Ant0_5320




Date: 27.OCT.2021 15:08:28

11AC20SISO_Ant0_5500




Date: 27.OCT.2021 15:10:08

11AC20SISO_Ant0_5580




Date: 27.OCT.2021 15:11:57

11AC20SISO_Ant0_5700




Date: 27.OCT.2021 15:13:20

11AC20SISO_Ant0_5720_UNII-2C




Date: 27.OCT.2021 15:15:09

11AC20SISO_Ant0_5745




Date: 27.OCT.2021 15:15:15

11AC20SISO_Ant0_5745




Date: 27.OCT.2021 15:21:38

11AC20SISO_Ant0_5785




Date: 27.OCT.2021 15:23:46

11AC20SISO_Ant0_5825




Date: 27.OCT.2021 15:25:30

11AC40SISO_Ant0_5190




Date: 27.OCT.2021 15:32:08

11AC40SISO_Ant0_5230




Date: 27.OCT.2021 15:34:12

11AC40SISO_Ant0_5270




Date: 27.OCT.2021 15:35:53

11AC40SISO_Ant0_5310




Date: 27.OCT.2021 15:38:29

11AC40SISO_Ant0_5510




Date: 27.OCT.2021 18:58:08

11AC40SISO_Ant0_5550




Date: 27.OCT.2021 19:00:42

11AC40SISO_Ant0_5670




Date: 27.OCT.2021 19:02:22

11AC40SISO_Ant0_5710_UNII-2C




Date: 27.OCT.2021 19:04:47

11AC40SISO_Ant0_5710_UNII-3




Date: 27.OCT.2021 19:04:53

11AC40SISO_Ant0_5755




Date: 27.OCT.2021 19:08:54

11AC40SISO_Ant0_5795




Date: 27.OCT.2021 19:11:00

11AC80SISO_Ant0_5210




Date: 27.OCT.2021 19:13:00

11AC80SISO_Ant0_5290




Date: 27.OCT.2021 19:14:59

11AC80SISO_Ant0_5530




Date: 27.OCT.2021 19:16:51

11AC80SISO_Ant0_5610




Date: 27.OCT.2021 19:19:01

11AC80SISO_Ant0_5690_UNII-2C




Date: 27.OCT.2021 19:21:12

11AC80SISO_Ant0_5690_UNII-3




Date: 27.OCT.2021 19:21:18

11AC80SISO_Ant0_5775




Date: 27.OCT.2021 19:23:39

11AX20SISO_Ant0_5180




Date: 27.OCT.2021 19:47:02

11AX40SISO_Ant0_5190




Date: 27.OCT.2021 21:07:04

11AX20SISO_Ant0_5200




Date: 27.OCT.2021 19:48:58

11AX80SISO_Ant0_5210




Date: 27.OCT.2021 21:27:25

11AX40SISO_Ant0_5230




Date: 27.OCT.2021 21:08:57

11AX20SISO_Ant0_5240




Date: 27.OCT.2021 19:50:39

11AX20SISO_Ant0_5260




Date: 27.OCT.2021 19:52:41

11AX40SISO_Ant0_5270



Date: 27.OCT.2021 21:10:27

11AX20SISO_Ant0_5280



Date: 27.OCT.2021 19:55:10

11AX80SISO_Ant0_5290