



Date: 28.OCT.2021 12:52:51

11N20SISO_Ant0_5280_5360~40000




Date: 28.OCT.2021 12:52:56

11N20SISO_Ant0_5320_30~5140




Date: 28.OCT.2021 13:24:10

11N20SISO_Ant0_5320_5360~40000




Date: 28.OCT.2021 13:24:15

11N40SISO_Ant0_5190_30~5140




Date: 28.OCT.2021 13:25:59

11N40SISO_Ant0_5190_5360~40000




Date: 28.OCT.2021 13:26:04

11N40SISO_Ant0_5230_30~5140




Date: 28.OCT.2021 13:27:28

11N40SISO_Ant0_5230_5360~40000




Date: 28.OCT.2021 13:27:33

11N40SISO_Ant0_5270_30~5140




Date: 28.OCT.2021 13:28:57

11N40SISO_Ant0_5270_5360~40000




Date: 28.OCT.2021 13:29:02

11N40SISO_Ant0_5310_30~5140




Date: 28.OCT.2021 13:31:03

11N40SISO_Ant0_5310_5360~40000




Date: 28.OCT.2021 13:31:09

11AC20SISO_Ant0_5180_30~5140




Date: 28.OCT.2021 13:33:39

11AC20SISO_Ant0_5180_5360~40000




Date: 28.OCT.2021 13:33:44

11AC20SISO_Ant0_5200_30~5140




Date: 28.OCT.2021 13:35:10

11AC20SISO_Ant0_5200_5360~40000




Date: 28.OCT.2021 13:35:15

11AC20SISO_Ant0_5240_30~5140




Date: 28.OCT.2021 14:33:16

11AC20SISO_Ant0_5240_5360~40000




Date: 28.OCT.2021 14:33:21

11AC20SISO_Ant0_5260_30~5140




Date: 28.OCT.2021 14:35:04

11AC20SISO_Ant0_5260_5360~40000




Date: 28.OCT.2021 14:35:09

11AC20SISO_Ant0_5280_30~5140




Date: 28.OCT.2021 14:37:02

11AC20SISO_Ant0_5280_5360~40000




Date: 28.OCT.2021 14:37:07

11AC20SISO_Ant0_5320_30-5140




Date: 28.OCT.2021 14:39:22

11AC20SISO_Ant0_5320_5360-40000




Date: 28.OCT.2021 14:39:27

11AC40SISO_Ant0_5190_30-5140




Date: 28.OCT.2021 14:41:09

11AC40SISO_Ant0_5190_5360~40000




Date: 28.OCT.2021 14:41:14

11AC40SISO_Ant0_5230_30~5140




Date: 28.OCT.2021 14:43:20

11AC40SISO_Ant0_5230_5360~40000




Date: 28.OCT.2021 14:43:25

11AC40SISO_Ant0_5270_30~5140




Date: 28.OCT.2021 14:44:57

11AC40SISO_Ant0_5270_5360~40000




Date: 28.OCT.2021 14:45:02

11AC40SISO_Ant0_5310_30~5140




Date: 28.OCT.2021 14:46:38

11AC40SISO_Ant0_5310_5360~40000




Date: 28.OCT.2021 14:46:43

11AC80SISO_Ant0_5210_30~5140




Date: 28.OCT.2021 14:48:43

11AC80SISO_Ant0_5210_5360~40000




Date: 28.OCT.2021 14:48:48

11AC80SISO_Ant0_5290_30~5140




Date: 28.OCT.2021 14:50:35

11AC80SISO_Ant0_5290_5360~40000




Date: 28.OCT.2021 14:50:40

11AX20SISO_Ant0_5180_30~5140




Date: 28.OCT.2021 14:52:17

11AX20SISO_Ant0_5180_5360~40000




Date: 28.OCT.2021 14:52:22

11AX40SISO_Ant0_5190_30~5140




Date: 28.OCT.2021 15:02:55

11AX40SISO_Ant0_5190_5360~40000




Date: 28.OCT.2021 15:03:00

11AX20SISO_Ant0_5200_30~5140




Date: 28.OCT.2021 14:53:48

11AX20SISO_Ant0_5200_5360~40000




Date: 28.OCT.2021 14:53:53

11AX80SISO_Ant0_5210_30~5140




Date: 28.OCT.2021 15:10:38

11AX80SISO_Ant0_5210_5360~40000




Date: 28.OCT.2021 15:10:43

11AX40SISO_Ant0_5230_30~5140




Date: 28.OCT.2021 15:05:00

11AX40SISO_Ant0_5230_5360~40000




Date: 28.OCT.2021 15:05:05

11AX20SISO_Ant0_5240_30~5140




Date: 28.OCT.2021 14:55:26

11AX20SISO_Ant0_5240_5360~40000




Date: 28.OCT.2021 14:55:31

11AX20SISO_Ant0_5260_30~5140




Date: 28.OCT.2021 14:56:58

11AX20SISO_Ant0_5260_5360~40000




Date: 28.OCT.2021 14:57:03

11AX40SISO_Ant0_5270_30~5140




Date: 28.OCT.2021 15:06:47

11AX40SISO_Ant0_5270_5360~40000




Date: 28.OCT.2021 15:06:52

11AX20SISO_Ant0_5280_30~5140




Date: 28.OCT.2021 14:58:43

11AX20SISO_Ant0_5280_5360~40000




Date: 28.OCT.2021 14:58:48

11AX80SISO_Ant0_5290_30~5140




Date: 28.OCT.2021 15:12:33

11AX80SISO_Ant0_5290_5360~40000




Date: 28.OCT.2021 15:12:39

11AX40SISO_Ant0_5310_30~5140




Date: 28.OCT.2021 15:08:34

11AX40SISO_Ant0_5310_5360~40000




Date: 28.OCT.2021 15:08:39

11AX20SISO_Ant0_5320_30~5140








Date: 28.OCT.2021 15:00:35

11AX20SISO_Ant0_5320_5360~40000




Date: 28.OCT.2021 15:00:40






Date: 28.OCT.2021 15:24:29

11A_Ant1_5240_30~5140




Date: 28.OCT.2021 15:26:20

11A_Ant1_5240_5360~40000




Date: 28.OCT.2021 15:26:25

11A_Ant1_5260_30~5140




Date: 28.OCT.2021 15:28:02

11A_Ant1_5260_5360~40000




Date: 28.OCT.2021 15:28:07

11A_Ant1_5280_30~5140




Date: 28.OCT.2021 15:29:45

11A_Ant1_5280_5360~40000




Date: 28.OCT.2021 15:29:50

11A_Ant1_5320_30~5140




Date: 28.OCT.2021 15:31:36

11A_Ant1_5320_5360~40000




Date: 28.OCT.2021 15:31:41

11N20MIMO_5180_30~5140




Date: 28.OCT.2021 15:33:45

11N20MIMO_5180_5360~40000




Date: 28.OCT.2021 15:33:50

11N20MIMO_5200_30~5140




Date: 28.OCT.2021 15:35:23

11N20MIMO_5200_5360~40000




Date: 28.OCT.2021 15:35:28

11N20MIMO_5240_30~5140




Date: 28.OCT.2021 15:36:50

11N20MIMO_5240_5360~40000




Date: 28.OCT.2021 15:36:55

11N20MIMO_5260_30~5140




Date: 28.OCT.2021 15:38:34

11N20MIMO_5260_5360~40000




Date: 28.OCT.2021 15:38:39

11N20MIMO_5280_30~5140




Date: 28.OCT.2021 15:40:00

11N20MIMO_5280_5360~40000




Date: 28.OCT.2021 15:40:05

11N20MIMO_5320_30~5140




Date: 28.OCT.2021 15:42:05

11N20MIMO_5320_5360~40000




Date: 28.OCT.2021 15:42:10

11N40MIMO_5190_30~5140




Date: 28.OCT.2021 15:43:57

11N40MIMO_5190_5360~40000




Date: 28.OCT.2021 15:44:02

11N40MIMO_5230_30~5140




Date: 28.OCT.2021 15:45:32

11N40MIMO_5230_5360~40000




Date: 28.OCT.2021 15:45:37

11N40MIMO_5270_30~5140




Date: 28.OCT.2021 15:47:22

11N40MIMO_5270_5360~40000




Date: 28.OCT.2021 15:47:27

11N40MIMO_5310_30~5140




Date: 28.OCT.2021 15:50:51

11N40MIMO_5310_5360~40000




Date: 28.OCT.2021 15:50:56

11AC20MIMO_5180_30~5140




Date: 28.OCT.2021 15:54:56

11AC20MIMO_5180_5360~40000




Date: 28.OCT.2021 15:55:01

11AC20MIMO_5200_30~5140




Date: 28.OCT.2021 15:56:38

11AC20MIMO_5200_5360~40000




Date: 28.OCT.2021 15:56:43

11AC20MIMO_5240_30~5140




Date: 28.OCT.2021 15:58:07

11AC20MIMO_5240_5360~40000




Date: 28.OCT.2021 15:58:12

11AC20MIMO_5260_30~5140




Date: 28.OCT.2021 15:59:36

11AC20MIMO_5260_5360~40000




Date: 28.OCT.2021 15:59:41

11AC20MIMO_5280_30~5140




Date: 28.OCT.2021 16:01:07

11AC20MIMO_5280_5360~40000




Date: 28.OCT.2021 16:01:12

11AC20MIMO_5320_30~5140




Date: 28.OCT.2021 16:03:00

11AC20MIMO_5320_5360~40000




Date: 28.OCT.2021 16:03:05

11AC40MIMO_5190_30~5140




Date: 28.OCT.2021 16:04:59

11AC40MIMO_5190_5360~40000




Date: 28.OCT.2021 16:05:04

11AC40MIMO_5230_30~5140




Date: 28.OCT.2021 16:06:29

11AC40MIMO_5230_5360~40000




Date: 28.OCT.2021 16:06:34

11AC40MIMO_5270_30~5140




Date: 28.OCT.2021 16:08:12

11AC40MIMO_5270_5360~40000




Date: 28.OCT.2021 16:08:17

11AC40MIMO_5310_30~5140




Date: 28.OCT.2021 16:09:56

11AC40MIMO_5310_5360~40000




Date: 28.OCT.2021 16:10:01

11AC80MIMO_5210_30~5140




Date: 28.OCT.2021 16:11:59

11AC80MIMO_5210_5360~40000




Date: 28.OCT.2021 16:12:04

11AC80MIMO_5290_30~5140




Date: 28.OCT.2021 16:13:52

11AC80MIMO_5290_5360~40000



Date: 28.OCT.2021 16:13:57

11AX20MIMO_5180_30~5140



Date: 28.OCT.2021 16:15:50

11AX20MIMO_5180_5360~40000