



Date: 27.OCT.2021 15:22:05

11AC20SISO_Ant0_5785_30~5650




Date: 27.OCT.2021 15:23:53

11AC20SISO_Ant0_5785_5925~40000




Date: 27.OCT.2021 15:23:58

11AC20SISO_Ant0_5825_30~5650




Date: 27.OCT.2021 15:25:52

11AC20SISO_Ant0_5825_5925~40000




Date: 27.OCT.2021 15:25:57

11AC40SISO_Ant0_5190_30~5140




Date: 27.OCT.2021 15:32:28

11AC40SISO_Ant0_5190_5360~40000




Date: 27.OCT.2021 15:32:34

11AC40SISO_Ant0_5230_30~5140




Date: 27.OCT.2021 15:34:19

11AC40SISO_Ant0_5230_5360~40000




Date: 27.OCT.2021 15:34:24

11AC40SISO_Ant0_5270_30~5140




Date: 27.OCT.2021 15:36:00

11AC40SISO_Ant0_5270_5360~40000




Date: 27.OCT.2021 15:36:05

11AC40SISO_Ant0_5310_30~5140




Date: 27.OCT.2021 15:38:50

11AC40SISO_Ant0_5310_5360~40000




Date: 27.OCT.2021 15:38:55

11AC40SISO_Ant0_5510_30~5460




Date: 27.OCT.2021 18:58:29

11AC40SISO_Ant0_5510_5735~40000




Date: 27.OCT.2021 18:58:34

11AC40SISO_Ant0_5550_30~5460




Date: 27.OCT.2021 19:00:49

11AC40SISO_Ant0_5550_5735~40000




Date: 27.OCT.2021 19:00:54

11AC40SISO_Ant0_5670_30~5460




Date: 27.OCT.2021 19:02:43

11AC40SISO_Ant0_5670_5735~40000




Date: 27.OCT.2021 19:02:48

11AC40SISO_Ant0_5710_30~5460




Date: 27.OCT.2021 19:05:27

11AC40SISO_Ant0_5710_5925~40000




Date: 27.OCT.2021 19:05:32

11AC40SISO_Ant0_5755_30~5650




Date: 27.OCT.2021 19:09:16

11AC40SISO_Ant0_5755_5925~40000




Date: 27.OCT.2021 19:09:21

11AC40SISO_Ant0_5795_30~5650




Date: 27.OCT.2021 19:11:23

11AC40SISO_Ant0_5795_5925~40000




Date: 27.OCT.2021 19:11:28

11AC80SISO_Ant0_5210_30~5140




Date: 27.OCT.2021 19:13:20

11AC80SISO_Ant0_5210_5360~40000




Date: 27.OCT.2021 19:13:25

11AC80SISO_Ant0_5290_30~5140




Date: 27.OCT.2021 19:15:20

11AC80SISO_Ant0_5290_5360~40000




Date: 27.OCT.2021 19:15:25

11AC80SISO_Ant0_5530_30~5460




Date: 27.OCT.2021 19:17:12

11AC80SISO_Ant0_5530_5735~40000




Date: 27.OCT.2021 19:17:17

11AC80SISO_Ant0_5610_30~5460




Date: 27.OCT.2021 19:19:21

11AC80SISO_Ant0_5610_5735~40000




Date: 27.OCT.2021 19:19:26

11AC80SISO_Ant0_5690_30~5460




Date: 27.OCT.2021 19:21:52

11AC80SISO_Ant0_5690_5925~40000




Date: 27.OCT.2021 19:21:57

11AC80SISO_Ant0_5775_30~5650




Date: 27.OCT.2021 19:24:16

11AC80SISO_Ant0_5775_5925~40000




Date: 27.OCT.2021 19:24:21

11AX20SISO_Ant0_5180_30~5140




Date: 27.OCT.2021 19:47:22

11AX20SISO_Ant0_5180_5360~40000




Date: 27.OCT.2021 19:47:27

11AX40SISO_Ant0_5190_30~5140




Date: 27.OCT.2021 21:07:24

11AX40SISO_Ant0_5190_5360~40000




Date: 27.OCT.2021 21:07:29

11AX20SISO_Ant0_5200_30~5140




Date: 27.OCT.2021 19:49:06

11AX20SISO_Ant0_5200_5360~40000




Date: 27.OCT.2021 19:49:11

11AX80SISO_Ant0_5210_30~5140




Date: 27.OCT.2021 21:27:45

11AX80SISO_Ant0_5210_5360~40000




Date: 27.OCT.2021 21:27:50

11AX40SISO_Ant0_5230_30~5140




Date: 27.OCT.2021 21:09:04

11AX40SISO_Ant0_5230_5360~40000




Date: 27.OCT.2021 21:09:09

11AX20SISO_Ant0_5240_30~5140




Date: 27.OCT.2021 19:50:46

11AX20SISO_Ant0_5240_5360~40000




Date: 27.OCT.2021 19:50:51

11AX20SISO_Ant0_5260_30-5140




Date: 27.OCT.2021 19:52:48

11AX20SISO_Ant0_5260_5360-40000




Date: 27.OCT.2021 19:52:53

11AX40SISO_Ant0_5270_30-5140




Date: 27.OCT.2021 21:10:35

11AX40SISO_Ant0_5270_5360~40000




Date: 27.OCT.2021 21:10:40

11AX20SISO_Ant0_5280_30~5140




Date: 27.OCT.2021 19:55:18

11AX20SISO_Ant0_5280_5360~40000




Date: 27.OCT.2021 19:55:23

11AX80SISO_Ant0_5290_30-5140




Date: 27.OCT.2021 21:30:22

11AX80SISO_Ant0_5290_5360-40000




Date: 27.OCT.2021 21:30:27

11AX40SISO_Ant0_5310_30-5140




Date: 27.OCT.2021 21:12:21

11AX40SISO_Ant0_5310_5360~40000




Date: 27.OCT.2021 21:12:26

11AX20SISO_Ant0_5320_30~5140




Date: 27.OCT.2021 19:57:33

11AX20SISO_Ant0_5320_5360~40000




Date: 27.OCT.2021 19:57:38

11AX20SISO_Ant0_5500_30~5460




Date: 27.OCT.2021 19:59:14

11AX20SISO_Ant0_5500_5735~40000




Date: 27.OCT.2021 19:59:19

11AX40SISO_Ant0_5510_30~5460




Date: 27.OCT.2021 21:14:29

11AX40SISO_Ant0_5510_5735~40000




Date: 27.OCT.2021 21:14:34

11AX80SISO_Ant0_5530_30~5460




Date: 27.OCT.2021 21:33:11

11AX80SISO_Ant0_5530_5735~40000




Date: 27.OCT.2021 21:33:16

11AX40SISO_Ant0_5550_30~5460




Date: 27.OCT.2021 21:16:10

11AX40SISO_Ant0_5550_5735~40000




Date: 27.OCT.2021 21:16:15

11AX20SISO_Ant0_5580_30~5460




Date: 27.OCT.2021 20:00:43

11AX20SISO_Ant0_5580_5735~40000




Date: 27.OCT.2021 20:00:49

11AX80SISO_Ant0_5610_30~5460




Date: 27.OCT.2021 21:37:15

11AX80SISO_Ant0_5610_5735~40000




Date: 27.OCT.2021 21:37:20

11AX40SISO_Ant0_5670_30~5460




Date: 27.OCT.2021 21:18:14

11AX40SISO_Ant0_5670_5735~40000




Date: 27.OCT.2021 21:18:20

11AX80SISO_Ant0_5690_30~5460




Date: 27.OCT.2021 21:40:18

11AX80SISO_Ant0_5690_5925~40000




Date: 27.OCT.2021 21:40:23

11AX20SISO_Ant0_5700_30~5460




Date: 27.OCT.2021 20:02:52

11AX20SISO_Ant0_5700_5735~40000




Date: 27.OCT.2021 20:02:57

11AX40SISO_Ant0_5710_30~5460




Date: 27.OCT.2021 21:20:56

11AX40SISO_Ant0_5710_5925~40000




Date: 27.OCT.2021 21:21:01

11AX20SISO_Ant0_5720_30~5460




Date: 27.OCT.2021 20:58:44

11AX20SISO_Ant0_5720_5925~40000




Date: 27.OCT.2021 20:58:49

11AX20SISO_Ant0_5745_30~5650




Date: 27.OCT.2021 21:00:56

11AX20SISO_Ant0_5745_5925~40000




Date: 27.OCT.2021 21:01:01

11AX40SISO_Ant0_5755_30~5650




Date: 27.OCT.2021 21:23:15

11AX40SISO_Ant0_5755_5925~40000




Date: 27.OCT.2021 21:23:20

11AX80SISO_Ant0_5775_30~5650




Date: 27.OCT.2021 21:46:42

11AX80SISO_Ant0_5775_5925~40000




Date: 27.OCT.2021 21:46:47

11AX20SISO_Ant0_5785_30~5650




Date: 27.OCT.2021 21:02:57

11AX20SISO_Ant0_5785_5925~40000




Date: 27.OCT.2021 21:03:03

11AX40SISO_Ant0_5795_30~5650




Date: 27.OCT.2021 21:25:37

11AX40SISO_Ant0_5795_5925~40000




Date: 27.OCT.2021 21:25:42

11AX20SISO_Ant0_5825_30~5650






Date: 27.OCT.2021 21:05:11


11AX20SISO_Ant0_5825_5925~40000



Date: 27.OCT.2021 21:05:16




11A_Ant1_5200_5360~40000




Date: 25.OCT.2021 14:58:13

11A_Ant1_5240_30~5140




Date: 25.OCT.2021 14:59:47

11A_Ant1_5240_5360~40000




Date: 25.OCT.2021 14:59:52

11A_Ant1_5260_30~5140




Date: 25.OCT.2021 15:01:30

11A_Ant1_5260_5360~40000




Date: 25.OCT.2021 15:01:35

11A_Ant1_5280_30~5140




Date: 25.OCT.2021 15:03:07

11A_Ant1_5280_5360~40000




Date: 25.OCT.2021 15:03:12

11A_Ant1_5320_30~5140




Date: 25.OCT.2021 15:04:57

11A_Ant1_5320_5360~40000




Date: 25.OCT.2021 15:05:02

11A_Ant1_5500_30~5460




Date: 25.OCT.2021 15:06:53

11A_Ant1_5500_5735-40000




Date: 25.OCT.2021 15:06:58

11A_Ant1_5580_30-5460




Date: 25.OCT.2021 15:10:11

11A_Ant1_5580_5735-40000




Date: 25.OCT.2021 15:10:16

11A_Ant1_5700_30~5460




Date: 25.OCT.2021 15:12:42

11A_Ant1_5700_5735~40000




Date: 25.OCT.2021 15:12:48

11A_Ant1_5720_30~5460




Date: 25.OCT.2021 15:16:41

11A_Ant1_5720_5925~40000



Date: 25.OCT.2021 15:16:46

11A_Ant1_5745_30~5650



Date: 25.OCT.2021 15:19:37

11A_Ant1_5745_5925~40000