



Date: 27.OCT.2021 12:43:05

11N20SISO\_Ant0\_5240\_30~5140




Date: 27.OCT.2021 12:44:33

11N20SISO\_Ant0\_5240\_5360~40000




Date: 27.OCT.2021 12:44:38

11N20SISO\_Ant0\_5260\_30~5140




Date: 27.OCT.2021 12:46:17

11N20SISO\_Ant0\_5260\_5360~40000




Date: 27.OCT.2021 12:46:22

11N20SISO\_Ant0\_5280\_30~5140




Date: 27.OCT.2021 12:47:56

11N20SISO\_Ant0\_5280\_5360~40000




Date: 27.OCT.2021 12:48:01

11N20SISO\_Ant0\_5320\_30~5140




Date: 27.OCT.2021 12:49:44

11N20SISO\_Ant0\_5320\_5360~40000




Date: 27.OCT.2021 12:49:49

11N20SISO\_Ant0\_5500\_30~5460




Date: 27.OCT.2021 12:52:48

11N20SISO\_Ant0\_5500\_5735~40000




Date: 27.OCT.2021 12:52:53

11N20SISO\_Ant0\_5580\_30~5460




Date: 27.OCT.2021 12:54:25

11N20SISO\_Ant0\_5580\_5735~40000




Date: 27.OCT.2021 12:54:31

11N20SISO\_Ant0\_5700\_30~5460




Date: 27.OCT.2021 12:56:25

11N20SISO\_Ant0\_5700\_5735~40000




Date: 27.OCT.2021 12:56:30

11N20SISO\_Ant0\_5720\_30~5460




Date: 27.OCT.2021 12:58:20

11N20SISO\_Ant0\_5720\_5925~40000




Date: 27.OCT.2021 12:58:25

11N20SISO\_Ant0\_5745\_30~5650




Date: 27.OCT.2021 13:00:11

11N20SISO\_Ant0\_5745\_5925~40000




Date: 27.OCT.2021 13:00:16

11N20SISO\_Ant0\_5785\_30~5650




Date: 27.OCT.2021 14:36:08

11N20SISO\_Ant0\_5785\_5925~40000




Date: 27.OCT.2021 14:36:14

11N20SISO\_Ant0\_5825\_30~5650




Date: 27.OCT.2021 14:38:03

11N20SISO\_Ant0\_5825\_5925~40000



Date: 27.OCT.2021 14:38:08


11N40SISO\_Ant0\_5190\_30~5140



Date: 27.OCT.2021 14:40:12


11N40SISO\_Ant0\_5190\_5360~40000






Date: 27.OCT.2021 14:40:17

11N40SISO\_Ant0\_5230\_30~5140




Date: 27.OCT.2021 14:42:06

11N40SISO\_Ant0\_5230\_5360~40000




Date: 27.OCT.2021 14:42:11

11N40SISO\_Ant0\_5270\_30~5140




Date: 27.OCT.2021 14:44:00

11N40SISO\_Ant0\_5270\_5360~40000




Date: 27.OCT.2021 14:44:05

11N40SISO\_Ant0\_5310\_30~5140




Date: 27.OCT.2021 14:46:02

11N40SISO\_Ant0\_5310\_5360~40000




Date: 27.OCT.2021 14:46:07

11N40SISO\_Ant0\_5510\_30~5460




Date: 27.OCT.2021 14:47:46

11N40SISO\_Ant0\_5510\_5735~40000




Date: 27.OCT.2021 14:47:51

11N40SISO\_Ant0\_5550\_30~5460




Date: 27.OCT.2021 14:50:15

11N40SISO\_Ant0\_5550\_5735~40000




Date: 27.OCT.2021 14:50:20

11N40SISO\_Ant0\_5670\_30~5460




Date: 27.OCT.2021 14:52:42

11N40SISO\_Ant0\_5670\_5735~40000




Date: 27.OCT.2021 14:52:47

11N40SISO\_Ant0\_5710\_30~5460




Date: 27.OCT.2021 14:54:41

11N40SISO\_Ant0\_5710\_5925~40000




Date: 27.OCT.2021 14:54:46

11N40SISO\_Ant0\_5755\_30~5650




Date: 27.OCT.2021 14:56:44

11N40SISO\_Ant0\_5755\_5925~40000




Date: 27.OCT.2021 14:56:49

11N40SISO\_Ant0\_5795\_30~5650




Date: 27.OCT.2021 14:58:41

11N40SISO\_Ant0\_5755\_5925~40000




Date: 27.OCT.2021 14:58:46

11AC20SISO\_Ant0\_5180\_30-5140




Date: 27.OCT.2021 15:00:19

11AC20SISO\_Ant0\_5180\_5360-40000




Date: 27.OCT.2021 15:00:24

11AC20SISO\_Ant0\_5200\_30-5140




Date: 27.OCT.2021 15:02:06

11AC20SISO\_Ant0\_5200\_5360~40000



Date: 27.OCT.2021 15:02:11


11AC20SISO\_Ant0\_5240\_30~5140



Date: 27.OCT.2021 15:03:35


11AC20SISO\_Ant0\_5240\_5360~40000






Date: 27.OCT.2021 15:03:40

11AC20SISO\_Ant0\_5260\_30~5140




Date: 27.OCT.2021 15:05:21

11AC20SISO\_Ant0\_5260\_5360~40000




Date: 27.OCT.2021 15:05:27

11AC20SISO\_Ant0\_5280\_30~5140




Date: 27.OCT.2021 15:06:55

11AC20SISO\_Ant0\_5280\_5360~40000




Date: 27.OCT.2021 15:07:01

11AC20SISO\_Ant0\_5320\_30~5140




Date: 27.OCT.2021 15:08:36

11AC20SISO\_Ant0\_5320\_5360~40000




Date: 27.OCT.2021 15:08:41

11AC20SISO\_Ant0\_5500\_30~5460




Date: 27.OCT.2021 15:10:16

11AC20SISO\_Ant0\_5500\_5735~40000




Date: 27.OCT.2021 15:10:21

11AC20SISO\_Ant0\_5580\_30~5460




Date: 27.OCT.2021 15:12:04

11AC20SISO\_Ant0\_5580\_5735~40000




Date: 27.OCT.2021 15:12:09

11AC20SISO\_Ant0\_5700\_30~5460




Date: 27.OCT.2021 15:13:27

11AC20SISO\_Ant0\_5700\_5735~40000




Date: 27.OCT.2021 15:13:32

11AC20SISO\_Ant0\_5720\_30~5460




Date: 27.OCT.2021 15:15:22

11AC20SISO\_Ant0\_5720\_5925~40000




Date: 27.OCT.2021 15:15:28

11AC20SISO\_Ant0\_5745\_30~5650




Date: 27.OCT.2021 15:22:00

11AC20SISO\_Ant0\_5745\_5925~40000




Date: 27.OCT.2021 15:22:05

11AC20SISO\_Ant0\_5785\_30~5650




Date: 27.OCT.2021 15:23:53

11AC20SISO\_Ant0\_5785\_5925~40000




Date: 27.OCT.2021 15:23:58

11AC20SISO\_Ant0\_5825\_30~5650




Date: 27.OCT.2021 15:25:52

11AC20SISO\_Ant0\_5825\_5925~40000




Date: 27.OCT.2021 15:25:57

11AC40SISO\_Ant0\_5190\_30~5140




Date: 27.OCT.2021 15:32:28

11AC40SISO\_Ant0\_5190\_5360~40000



Date: 27.OCT.2021 15:32:34


11AC40SISO\_Ant0\_5230\_30~5140



Date: 27.OCT.2021 15:34:19


11AC40SISO\_Ant0\_5230\_5360~40000






Date: 27.OCT.2021 15:34:24

11AC40SISO\_Ant0\_5270\_30~5140




Date: 27.OCT.2021 15:36:00

11AC40SISO\_Ant0\_5270\_5360~40000




Date: 27.OCT.2021 15:36:05

11AC40SISO\_Ant0\_5310\_30~5140




Date: 27.OCT.2021 15:38:50

11AC40SISO\_Ant0\_5310\_5360~40000




Date: 27.OCT.2021 15:38:55

11AC40SISO\_Ant0\_5510\_30~5460




Date: 27.OCT.2021 18:58:29

11AC40SISO\_Ant0\_5510\_5735~40000




Date: 27.OCT.2021 18:58:34

11AC40SISO\_Ant0\_5550\_30-5460




Date: 27.OCT.2021 19:00:49

11AC40SISO\_Ant0\_5550\_5735-40000




Date: 27.OCT.2021 19:00:54

11AC40SISO\_Ant0\_5670\_30-5460




Date: 27.OCT.2021 19:02:43

11AC40SISO\_Ant0\_5670\_5735~40000




Date: 27.OCT.2021 19:02:48

11AC40SISO\_Ant0\_5710\_30~5460




Date: 27.OCT.2021 19:05:27

11AC40SISO\_Ant0\_5710\_5925~40000




Date: 27.OCT.2021 19:05:32

11AC40SISO\_Ant0\_5755\_30~5650




Date: 27.OCT.2021 19:09:16

11AC40SISO\_Ant0\_5755\_5925~40000




Date: 27.OCT.2021 19:09:21

11AC40SISO\_Ant0\_5795\_30~5650




Date: 27.OCT.2021 19:11:23

11AC40SISO\_Ant0\_5795\_5925~40000




Date: 27.OCT.2021 19:11:28

11AC80SISO\_Ant0\_5210\_30~5140




Date: 27.OCT.2021 19:13:20

11AC80SISO\_Ant0\_5210\_5360~40000




Date: 27.OCT.2021 19:13:25

11AC80SISO\_Ant0\_5290\_30~5140




Date: 27.OCT.2021 19:15:20

11AC80SISO\_Ant0\_5290\_5360~40000




Date: 27.OCT.2021 19:15:25

11AC80SISO\_Ant0\_5530\_30~5460




Date: 27.OCT.2021 19:17:12

11AC80SISO\_Ant0\_5530\_5735~40000



Date: 27.OCT.2021 19:17:17


11AC80SISO\_Ant0\_5610\_30~5460



Date: 27.OCT.2021 19:19:21


11AC80SISO\_Ant0\_5610\_5735~40000






Date: 27.OCT.2021 19:19:26

11AC80SISO\_Ant0\_5690\_30~5460




Date: 27.OCT.2021 19:21:52

11AC80SISO\_Ant0\_5690\_5925~40000




Date: 27.OCT.2021 19:21:57

11AC80SISO\_Ant0\_5775\_30~5650




Date: 27.OCT.2021 19:24:16

11AC80SISO\_Ant0\_5775\_5925~40000




Date: 27.OCT.2021 19:24:21

11AX20SISO\_Ant0\_5180\_30~5140




Date: 27.OCT.2021 19:47:22

11AX20SISO\_Ant0\_5180\_5360~40000




Date: 27.OCT.2021 19:47:27

11AX40SISO\_Ant0\_5190\_30~5140




Date: 27.OCT.2021 21:07:24

11AX40SISO\_Ant0\_5190\_5360~40000




Date: 27.OCT.2021 21:07:29

11AX20SISO\_Ant0\_5200\_30~5140




Date: 27.OCT.2021 19:49:06

11AX20SISO\_Ant0\_5200\_5360~40000




Date: 27.OCT.2021 19:49:11

11AX80SISO\_Ant0\_5210\_30~5140




Date: 27.OCT.2021 21:27:45

11AX80SISO\_Ant0\_5210\_5360~40000




Date: 27.OCT.2021 21:27:50

11AX40SISO\_Ant0\_5230\_30~5140




Date: 27.OCT.2021 21:09:04

11AX40SISO\_Ant0\_5230\_5360~40000




Date: 27.OCT.2021 21:09:09

11AX20SISO\_Ant0\_5240\_30~5140




Date: 27.OCT.2021 19:50:46

11AX20SISO\_Ant0\_5240\_5360~40000




Date: 27.OCT.2021 19:50:51

11AX20SISO\_Ant0\_5260\_30~5140




Date: 27.OCT.2021 19:52:48

11AX20SISO\_Ant0\_5260\_5360~40000




Date: 27.OCT.2021 19:52:53

11AX40SISO\_Ant0\_5270\_30~5140



Date: 27.OCT.2021 21:10:35

11AX40SISO\_Ant0\_5270\_5360~40000



Date: 27.OCT.2021 21:10:40

11AX20SISO\_Ant0\_5280\_30~5140