







Band38_10MHz_QPSK_37800_1RB#49




Band38_10MHz_16QAM_37800_1RB#49




Band38_10MHz_QPSK_37800_50RB#0



Band38_10MHz_16QAM_37800_50RB#0




Band38_10MHz_QPSK_38200_1RB#0




Band38_10MHz_16QAM_38200_1RB#0


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band38_10MHz_QPSK_38200_1RB#49




Band38_10MHz_16QAM_38200_1RB#49




Band38_10MHz_QPSK_38200_50RB#0



Band38_10MHz_16QAM_38200_50RB#0




Band38_15MHz_QPSK_37825_1RB#0




Band38_15MHz_16QAM_37825_1RB#0


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band38_15MHz_QPSK_37825_1RB#74




Band38_15MHz_16QAM_37825_1RB#74




Band38_15MHz_QPSK_37825_75RB#0



Band38_15MHz_16QAM_37825_75RB#0




Band38_15MHz_QPSK_38175_1RB#0




Band38_15MHz_16QAM_38175_1RB#0


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band38_15MHz_QPSK_38175_1RB#74




Band38_15MHz_16QAM_38175_1RB#74




Band38_15MHz_QPSK_38175_75RB#0



Band38_15MHz_16QAM_38175_75RB#0




Band38_20MHz_QPSK_37850_1RB#0




Band38_20MHz_16QAM_37850_1RB#0


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.




Band38_20MHz_QPSK_37850_1RB#99




Band38_20MHz_16QAM_37850_1RB#99




Band38_20MHz_QPSK_37850_100RB#0



Band38_20MHz_16QAM_37850_100RB#0




Band38_20MHz_QPSK_38150_1RB#0



Band38_20MHz_16QAM_38150_1RB#0

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: <http://www.agccert.com/>

Appendix E: Conducted Spurious Emission

Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Frequency Range	Result (dBm)	Verdict
Band38	5MHz	QPSK	37775	1RB#0	30~1000	-62.21	PASS
Band38	5MHz	QPSK	37775	1RB#0	1000~20000	-39.97	PASS
Band38	5MHz	QPSK	37775	1RB#0	20000~27000	-37.40	PASS
Band38	5MHz	16QAM	37775	1RB#0	30~1000	-62.26	PASS
Band38	5MHz	16QAM	37775	1RB#0	1000~20000	-39.73	PASS
Band38	5MHz	16QAM	37775	1RB#0	20000~27000	-37.80	PASS
Band38	5MHz	QPSK	37775	1RB#24	30~1000	-62.16	PASS
Band38	5MHz	QPSK	37775	1RB#24	1000~20000	-39.79	PASS
Band38	5MHz	QPSK	37775	1RB#24	20000~27000	-37.58	PASS
Band38	5MHz	16QAM	37775	1RB#24	30~1000	-62.24	PASS
Band38	5MHz	16QAM	37775	1RB#24	1000~20000	-39.66	PASS
Band38	5MHz	16QAM	37775	1RB#24	20000~27000	-37.69	PASS
Band38	5MHz	QPSK	37775	25RB#0	30~1000	-62.04	PASS
Band38	5MHz	QPSK	37775	25RB#0	1000~20000	-35.52	PASS
Band38	5MHz	QPSK	37775	25RB#0	20000~27000	-37.83	PASS
Band38	5MHz	16QAM	37775	25RB#0	30~1000	-62.31	PASS
Band38	5MHz	16QAM	37775	25RB#0	1000~20000	-40.17	PASS
Band38	5MHz	16QAM	37775	25RB#0	20000~27000	-37.31	PASS
Band38	5MHz	QPSK	38000	1RB#0	0.009~0.15	-39.07	FAIL
Band38	5MHz	QPSK	38000	1RB#0	0.15~30	-55.60	PASS
Band38	5MHz	QPSK	38000	1RB#0	30~1000	-61.85	PASS
Band38	5MHz	QPSK	38000	1RB#0	1000~20000	-39.82	PASS
Band38	5MHz	QPSK	38000	1RB#0	20000~27000	-37.59	PASS
Band38	5MHz	16QAM	38000	1RB#0	30~1000	-62.25	PASS
Band38	5MHz	16QAM	38000	1RB#0	1000~20000	-39.83	PASS
Band38	5MHz	16QAM	38000	1RB#0	20000~27000	-37.67	PASS
Band38	5MHz	QPSK	38000	1RB#24	30~1000	-62.31	PASS
Band38	5MHz	QPSK	38000	1RB#24	1000~20000	-39.64	PASS
Band38	5MHz	QPSK	38000	1RB#24	20000~27000	-37.37	PASS
Band38	5MHz	16QAM	38000	1RB#24	30~1000	-62.03	PASS
Band38	5MHz	16QAM	38000	1RB#24	1000~20000	-39.83	PASS
Band38	5MHz	16QAM	38000	1RB#24	20000~27000	-37.70	PASS
Band38	5MHz	QPSK	38000	25RB#0	30~1000	-62.41	PASS
Band38	5MHz	QPSK	38000	25RB#0	1000~20000	-38.33	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band38	5MHz	QPSK	38000	25RB#0	20000~27000	-37.96	PASS
Band38	5MHz	16QAM	38000	25RB#0	30~1000	-61.98	PASS
Band38	5MHz	16QAM	38000	25RB#0	1000~20000	-39.22	PASS
Band38	5MHz	16QAM	38000	25RB#0	20000~27000	-37.73	PASS
Band38	5MHz	QPSK	38225	1RB#0	30~1000	-62.18	PASS
Band38	5MHz	QPSK	38225	1RB#0	1000~20000	-39.78	PASS
Band38	5MHz	QPSK	38225	1RB#0	20000~27000	-38.01	PASS
Band38	5MHz	16QAM	38225	1RB#0	30~1000	-62.03	PASS
Band38	5MHz	16QAM	38225	1RB#0	1000~20000	-39.78	PASS
Band38	5MHz	16QAM	38225	1RB#0	20000~27000	-37.63	PASS
Band38	5MHz	QPSK	38225	1RB#24	30~1000	-61.88	PASS
Band38	5MHz	QPSK	38225	1RB#24	1000~20000	-39.82	PASS
Band38	5MHz	QPSK	38225	1RB#24	20000~27000	-37.85	PASS
Band38	5MHz	16QAM	38225	1RB#24	30~1000	-62.03	PASS
Band38	5MHz	16QAM	38225	1RB#24	1000~20000	-40.04	PASS
Band38	5MHz	16QAM	38225	1RB#24	20000~27000	-37.41	PASS
Band38	5MHz	QPSK	38225	25RB#0	30~1000	-62.38	PASS
Band38	5MHz	QPSK	38225	25RB#0	1000~20000	-39.96	PASS
Band38	5MHz	QPSK	38225	25RB#0	20000~27000	-37.68	PASS
Band38	5MHz	16QAM	38225	25RB#0	30~1000	-61.98	PASS
Band38	5MHz	16QAM	38225	25RB#0	1000~20000	-38.48	PASS
Band38	5MHz	16QAM	38225	25RB#0	20000~27000	-37.50	PASS
Band38	10MHz	QPSK	37800	1RB#0	30~1000	-62.21	PASS
Band38	10MHz	QPSK	37800	1RB#0	1000~20000	-39.70	PASS
Band38	10MHz	QPSK	37800	1RB#0	20000~27000	-37.61	PASS
Band38	10MHz	16QAM	37800	1RB#0	30~1000	-61.66	PASS
Band38	10MHz	16QAM	37800	1RB#0	1000~20000	-39.83	PASS
Band38	10MHz	16QAM	37800	1RB#0	20000~27000	-37.58	PASS
Band38	10MHz	QPSK	37800	1RB#49	30~1000	-62.40	PASS
Band38	10MHz	QPSK	37800	1RB#49	1000~20000	-39.46	PASS
Band38	10MHz	QPSK	37800	1RB#49	20000~27000	-37.83	PASS
Band38	10MHz	16QAM	37800	1RB#49	30~1000	-62.09	PASS
Band38	10MHz	16QAM	37800	1RB#49	1000~20000	-39.73	PASS
Band38	10MHz	16QAM	37800	1RB#49	20000~27000	-37.25	PASS
Band38	10MHz	QPSK	37800	50RB#0	30~1000	-61.95	PASS
Band38	10MHz	QPSK	37800	50RB#0	1000~20000	-39.74	PASS
Band38	10MHz	QPSK	37800	50RB#0	20000~27000	-37.65	PASS
Band38	10MHz	16QAM	37800	50RB#0	30~1000	-61.88	PASS
Band38	10MHz	16QAM	37800	50RB#0	1000~20000	-39.77	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band38	10MHz	16QAM	37800	50RB#0	20000~27000	-37.29	PASS
Band38	10MHz	QPSK	38000	1RB#0	30~1000	-62.21	PASS
Band38	10MHz	QPSK	38000	1RB#0	1000~20000	-39.72	PASS
Band38	10MHz	QPSK	38000	1RB#0	20000~27000	-37.69	PASS
Band38	10MHz	16QAM	38000	1RB#0	30~1000	-61.97	PASS
Band38	10MHz	16QAM	38000	1RB#0	1000~20000	-40.02	PASS
Band38	10MHz	16QAM	38000	1RB#0	20000~27000	-37.42	PASS
Band38	10MHz	QPSK	38000	1RB#49	30~1000	-62.07	PASS
Band38	10MHz	QPSK	38000	1RB#49	1000~20000	-40.07	PASS
Band38	10MHz	QPSK	38000	1RB#49	20000~27000	-37.63	PASS
Band38	10MHz	16QAM	38000	1RB#49	30~1000	-62.19	PASS
Band38	10MHz	16QAM	38000	1RB#49	1000~20000	-39.93	PASS
Band38	10MHz	16QAM	38000	1RB#49	20000~27000	-37.40	PASS
Band38	10MHz	QPSK	38000	50RB#0	30~1000	-62.21	PASS
Band38	10MHz	QPSK	38000	50RB#0	1000~20000	-39.82	PASS
Band38	10MHz	QPSK	38000	50RB#0	20000~27000	-37.77	PASS
Band38	10MHz	16QAM	38000	50RB#0	30~1000	-62.05	PASS
Band38	10MHz	16QAM	38000	50RB#0	1000~20000	-39.70	PASS
Band38	10MHz	16QAM	38000	50RB#0	20000~27000	-37.32	PASS
Band38	10MHz	QPSK	38200	1RB#0	30~1000	-62.20	PASS
Band38	10MHz	QPSK	38200	1RB#0	1000~20000	-39.75	PASS
Band38	10MHz	QPSK	38200	1RB#0	20000~27000	-37.84	PASS
Band38	10MHz	16QAM	38200	1RB#0	30~1000	-62.07	PASS
Band38	10MHz	16QAM	38200	1RB#0	1000~20000	-39.70	PASS
Band38	10MHz	16QAM	38200	1RB#0	20000~27000	-37.40	PASS
Band38	10MHz	QPSK	38200	1RB#49	30~1000	-62.19	PASS
Band38	10MHz	QPSK	38200	1RB#49	1000~20000	-39.85	PASS
Band38	10MHz	QPSK	38200	1RB#49	20000~27000	-37.47	PASS
Band38	10MHz	16QAM	38200	1RB#49	30~1000	-61.94	PASS
Band38	10MHz	16QAM	38200	1RB#49	1000~20000	-39.71	PASS
Band38	10MHz	16QAM	38200	1RB#49	20000~27000	-37.64	PASS
Band38	10MHz	QPSK	38200	50RB#0	30~1000	-61.93	PASS
Band38	10MHz	QPSK	38200	50RB#0	1000~20000	-39.68	PASS
Band38	10MHz	QPSK	38200	50RB#0	20000~27000	-37.68	PASS
Band38	10MHz	16QAM	38200	50RB#0	30~1000	-62.20	PASS
Band38	10MHz	16QAM	38200	50RB#0	1000~20000	-39.80	PASS
Band38	10MHz	16QAM	38200	50RB#0	20000~27000	-37.75	PASS
Band38	15MHz	QPSK	37825	1RB#0	30~1000	-62.23	PASS
Band38	15MHz	QPSK	37825	1RB#0	1000~20000	-39.62	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Band38	15MHz	QPSK	37825	1RB#0	20000~27000	-37.67	PASS
Band38	15MHz	16QAM	37825	1RB#0	30~1000	-61.86	PASS
Band38	15MHz	16QAM	37825	1RB#0	1000~20000	-39.63	PASS
Band38	15MHz	16QAM	37825	1RB#0	20000~27000	-37.85	PASS
Band38	15MHz	QPSK	37825	1RB#74	30~1000	-61.76	PASS
Band38	15MHz	QPSK	37825	1RB#74	1000~20000	-39.52	PASS
Band38	15MHz	QPSK	37825	1RB#74	20000~27000	-37.66	PASS
Band38	15MHz	16QAM	37825	1RB#74	30~1000	-61.81	PASS
Band38	15MHz	16QAM	37825	1RB#74	1000~20000	-39.71	PASS
Band38	15MHz	16QAM	37825	1RB#74	20000~27000	-37.62	PASS
Band38	15MHz	QPSK	37825	75RB#0	30~1000	-62.13	PASS
Band38	15MHz	QPSK	37825	75RB#0	1000~20000	-37.93	PASS
Band38	15MHz	QPSK	37825	75RB#0	20000~27000	-37.63	PASS
Band38	15MHz	16QAM	37825	75RB#0	30~1000	-62.23	PASS
Band38	15MHz	16QAM	37825	75RB#0	1000~20000	-38.31	PASS
Band38	15MHz	16QAM	37825	75RB#0	20000~27000	-37.80	PASS
Band38	15MHz	QPSK	38000	1RB#0	30~1000	-62.47	PASS
Band38	15MHz	QPSK	38000	1RB#0	1000~20000	-39.39	PASS
Band38	15MHz	QPSK	38000	1RB#0	20000~27000	-37.87	PASS
Band38	15MHz	16QAM	38000	1RB#0	30~1000	-62.30	PASS
Band38	15MHz	16QAM	38000	1RB#0	1000~20000	-39.84	PASS
Band38	15MHz	16QAM	38000	1RB#0	20000~27000	-37.60	PASS
Band38	15MHz	QPSK	38000	1RB#74	30~1000	-61.95	PASS
Band38	15MHz	QPSK	38000	1RB#74	1000~20000	-39.78	PASS
Band38	15MHz	QPSK	38000	1RB#74	20000~27000	-37.77	PASS
Band38	15MHz	16QAM	38000	1RB#74	30~1000	-62.16	PASS
Band38	15MHz	16QAM	38000	1RB#74	1000~20000	-39.56	PASS
Band38	15MHz	16QAM	38000	1RB#74	20000~27000	-37.57	PASS
Band38	15MHz	QPSK	38000	75RB#0	30~1000	-62.29	PASS
Band38	15MHz	QPSK	38000	75RB#0	1000~20000	-39.33	PASS
Band38	15MHz	QPSK	38000	75RB#0	20000~27000	-37.70	PASS
Band38	15MHz	16QAM	38000	75RB#0	30~1000	-62.40	PASS
Band38	15MHz	16QAM	38000	75RB#0	1000~20000	-39.66	PASS
Band38	15MHz	16QAM	38000	75RB#0	20000~27000	-37.67	PASS
Band38	15MHz	QPSK	38175	1RB#0	30~1000	-62.42	PASS
Band38	15MHz	QPSK	38175	1RB#0	1000~20000	-39.78	PASS
Band38	15MHz	QPSK	38175	1RB#0	20000~27000	-37.75	PASS
Band38	15MHz	16QAM	38175	1RB#0	30~1000	-62.05	PASS
Band38	15MHz	16QAM	38175	1RB#0	1000~20000	-39.79	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


Band38	15MHz	16QAM	38175	1RB#0	20000~27000	-37.46	PASS
Band38	15MHz	QPSK	38175	1RB#74	30~1000	-62.34	PASS
Band38	15MHz	QPSK	38175	1RB#74	1000~20000	-39.96	PASS
Band38	15MHz	QPSK	38175	1RB#74	20000~27000	-37.49	PASS
Band38	15MHz	16QAM	38175	1RB#74	30~1000	-62.15	PASS
Band38	15MHz	16QAM	38175	1RB#74	1000~20000	-39.47	PASS
Band38	15MHz	16QAM	38175	1RB#74	20000~27000	-37.21	PASS
Band38	15MHz	QPSK	38175	75RB#0	30~1000	-62.37	PASS
Band38	15MHz	QPSK	38175	75RB#0	1000~20000	-37.56	PASS
Band38	15MHz	QPSK	38175	75RB#0	20000~27000	-37.59	PASS
Band38	15MHz	16QAM	38175	75RB#0	30~1000	-61.94	PASS
Band38	15MHz	16QAM	38175	75RB#0	1000~20000	-38.99	PASS
Band38	15MHz	16QAM	38175	75RB#0	20000~27000	-37.52	PASS
Band38	20MHz	QPSK	37850	1RB#0	30~1000	-62.35	PASS
Band38	20MHz	QPSK	37850	1RB#0	1000~20000	-39.54	PASS
Band38	20MHz	QPSK	37850	1RB#0	20000~27000	-37.83	PASS
Band38	20MHz	16QAM	37850	1RB#0	30~1000	-62.23	PASS
Band38	20MHz	16QAM	37850	1RB#0	1000~20000	-39.59	PASS
Band38	20MHz	16QAM	37850	1RB#0	20000~27000	-37.38	PASS
Band38	20MHz	QPSK	37850	1RB#99	30~1000	-62.11	PASS
Band38	20MHz	QPSK	37850	1RB#99	1000~20000	-39.60	PASS
Band38	20MHz	QPSK	37850	1RB#99	20000~27000	-37.66	PASS
Band38	20MHz	16QAM	37850	1RB#99	30~1000	-62.61	PASS
Band38	20MHz	16QAM	37850	1RB#99	1000~20000	-39.73	PASS
Band38	20MHz	16QAM	37850	1RB#99	20000~27000	-37.51	PASS
Band38	20MHz	QPSK	37850	100RB#0	30~1000	-62.20	PASS
Band38	20MHz	QPSK	37850	100RB#0	1000~20000	-39.49	PASS
Band38	20MHz	QPSK	37850	100RB#0	20000~27000	-37.53	PASS
Band38	20MHz	16QAM	37850	100RB#0	30~1000	-62.69	PASS
Band38	20MHz	16QAM	37850	100RB#0	1000~20000	-39.73	PASS
Band38	20MHz	16QAM	37850	100RB#0	20000~27000	-37.80	PASS
Band38	20MHz	QPSK	38000	1RB#0	30~1000	-62.21	PASS
Band38	20MHz	QPSK	38000	1RB#0	1000~20000	-39.74	PASS
Band38	20MHz	QPSK	38000	1RB#0	20000~27000	-37.33	PASS
Band38	20MHz	16QAM	38000	1RB#0	30~1000	-62.16	PASS
Band38	20MHz	16QAM	38000	1RB#0	1000~20000	-39.54	PASS
Band38	20MHz	16QAM	38000	1RB#0	20000~27000	-37.52	PASS
Band38	20MHz	QPSK	38000	1RB#99	30~1000	-62.35	PASS
Band38	20MHz	QPSK	38000	1RB#99	1000~20000	-39.76	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


Band38	20MHz	QPSK	38000	1RB#99	20000~27000	-37.29	PASS
Band38	20MHz	16QAM	38000	1RB#99	30~1000	-62.60	PASS
Band38	20MHz	16QAM	38000	1RB#99	1000~20000	-39.70	PASS
Band38	20MHz	16QAM	38000	1RB#99	20000~27000	-37.68	PASS
Band38	20MHz	QPSK	38000	100RB#0	30~1000	-62.27	PASS
Band38	20MHz	QPSK	38000	100RB#0	1000~20000	-39.60	PASS
Band38	20MHz	QPSK	38000	100RB#0	20000~27000	-37.59	PASS
Band38	20MHz	16QAM	38000	100RB#0	30~1000	-62.54	PASS
Band38	20MHz	16QAM	38000	100RB#0	1000~20000	-39.42	PASS
Band38	20MHz	16QAM	38000	100RB#0	20000~27000	-37.59	PASS
Band38	20MHz	QPSK	38150	1RB#0	30~1000	-62.38	PASS
Band38	20MHz	QPSK	38150	1RB#0	1000~20000	-39.35	PASS
Band38	20MHz	QPSK	38150	1RB#0	20000~27000	-37.79	PASS
Band38	20MHz	16QAM	38150	1RB#0	30~1000	-62.63	PASS
Band38	20MHz	16QAM	38150	1RB#0	1000~20000	-39.51	PASS
Band38	20MHz	16QAM	38150	1RB#0	20000~27000	-37.52	PASS
Band38	20MHz	QPSK	38150	1RB#99	30~1000	-62.19	PASS
Band38	20MHz	QPSK	38150	1RB#99	1000~20000	-39.70	PASS
Band38	20MHz	QPSK	38150	1RB#99	20000~27000	-37.76	PASS
Band38	20MHz	16QAM	38150	1RB#99	30~1000	-62.51	PASS
Band38	20MHz	16QAM	38150	1RB#99	1000~20000	-39.67	PASS
Band38	20MHz	16QAM	38150	1RB#99	20000~27000	-37.70	PASS
Band38	20MHz	QPSK	38150	100RB#0	30~1000	-62.23	PASS
Band38	20MHz	QPSK	38150	100RB#0	1000~20000	-39.80	PASS
Band38	20MHz	QPSK	38150	100RB#0	20000~27000	-37.63	PASS
Band38	20MHz	16QAM	38150	100RB#0	30~1000	-62.73	PASS
Band38	20MHz	16QAM	38150	100RB#0	1000~20000	-39.94	PASS
Band38	20MHz	16QAM	38150	100RB#0	20000~27000	-37.88	PASS

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Test Graphs




Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.







Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.





Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: <http://www.agccert.com/>



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


	/
Band38_5MHz_QPSK_37775_25RB#0_20000~27000_20000~27000	/
/	
/	Band38_5MHz_16QAM_37775_25RB#0_30~1000_30~1000
	
Band38_5MHz_16QAM_37775_25RB#0_1000~20000_1000~20000	Band38_5MHz_16QAM_37775_25RB#0_20000~27000_20000~27000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


	
Band38_5MHz_QPSK_38000_1RB#0_30~1000_30~1000	Band38_5MHz_QPSK_38000_1RB#0_1000~20000_1000~20000
	/
Band38_5MHz_QPSK_38000_1RB#0_20000~27000_20000~27000	/
/	
/	Band38_5MHz_16QAM_38000_1RB#0_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.





Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: <http://www.agccert.com/>







Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


	
Band38_5MHz_QPSK_38000_25RB#0_20000~27000_20000~27000	/
	
/	Band38_5MHz_16QAM_38000_25RB#0_30~1000_30~1000
	
Band38_5MHz_16QAM_38000_25RB#0_1000~20000_1000~20000	Band38_5MHz_16QAM_38000_25RB#0_20000~27000_20000~27000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


	
Band38_5MHz_QPSK_38225_1RB#0_30~1000_30~1000	Band38_5MHz_QPSK_38225_1RB#0_1000~20000_1000~20000
	/
Band38_5MHz_QPSK_38225_1RB#0_20000~27000_20000~27000	/
/	
/	Band38_5MHz_16QAM_38225_1RB#0_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: <http://www.agccert.com/>



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.