









	
Band38_5MHz_QPSK_38225_25RB#0_20000~27000_20000~27000	/
	
/	Band38_5MHz_16QAM_38225_25RB#0_30~1000_30~1000
	
Band38_5MHz_16QAM_38225_25RB#0_1000~20000_1000~20000	Band38_5MHz_16QAM_38225_25RB#0_20000~27000_20000~27000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


	
Band38_10MHz_QPSK_37800_1RB#0_30~1000_30~1000	Band38_10MHz_QPSK_37800_1RB#0_1000~20000_1000~20000
	/
Band38_10MHz_QPSK_37800_1RB#0_20000~27000_20000~27000	/
/	
/	Band38_10MHz_16QAM_37800_1RB#0_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.





Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: <http://www.agccert.com/>

	
Band38_10MHz_16QAM_37800_1RB#0_1000~20000_1000~20000	Band38_10MHz_16QAM_37800_1RB#0_20000~27000_20000~27000
	
Band38_10MHz_QPSK_37800_1RB#49_30~1000_30~1000	Band38_10MHz_QPSK_37800_1RB#49_1000~20000_1000~20000
	/
Band38_10MHz_QPSK_37800_1RB#49_20000~27000_20000~27000	/





Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


	
Band38_10MHz_QPSK_37800_50RB#0_20000~27000_20000~27000	/
	
/	Band38_10MHz_16QAM_37800_50RB#0_30~1000_30~1000
	
Band38_10MHz_16QAM_37800_50RB#0_1000~20000_1000~20000	Band38_10MHz_16QAM_37800_50RB#0_20000~27000_20000~27000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


	
Band38_10MHz_QPSK_38000_1RB#0_30~1000_30~1000	Band38_10MHz_QPSK_38000_1RB#0_1000~20000_1000~20000
	/
Band38_10MHz_QPSK_38000_1RB#0_20000~27000_20000~27000	/
/	
/	Band38_10MHz_16QAM_38000_1RB#0_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.





Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: <http://www.agccert.com/>







Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.






	/
Band38_10MHz_QPSK_38000_50RB#0_20000~27000_20000~27000	/
/	
/	Band38_10MHz_16QAM_38000_50RB#0_30~1000_30~1000
	
Band38_10MHz_16QAM_38000_50RB#0_1000~20000_1000~20000	Band38_10MHz_16QAM_38000_50RB#0_20000~27000_20000~27000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


	
Band38_10MHz_QPSK_38200_1RB#0_30~1000_30~1000	Band38_10MHz_QPSK_38200_1RB#0_1000~20000_1000~20000
	/
Band38_10MHz_QPSK_38200_1RB#0_20000~27000_20000~27000	/
/	
/	Band38_10MHz_16QAM_38200_1RB#0_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.





Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: <http://www.agccert.com/>

	
Band38_10MHz_16QAM_38200_1RB#0_1000~20000_1000~20000	Band38_10MHz_16QAM_38200_1RB#0_20000~27000_20000~27000
	
Band38_10MHz_QPSK_38200_1RB#49_30~1000_30~1000	Band38_10MHz_QPSK_38200_1RB#49_1000~20000_1000~20000
	/
Band38_10MHz_QPSK_38200_1RB#49_20000~27000_20000~27000	/





Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.








Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

	/
Band38_10MHz_QPSK_38200_50RB#0_20000~27000_20000~27000	/
/	
/	Band38_10MHz_16QAM_38200_50RB#0_30~1000_30~1000
	
Band38_10MHz_16QAM_38200_50RB#0_1000~20000_1000~20000	Band38_10MHz_16QAM_38200_50RB#0_20000~27000_20000~27000


Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

	
Band38_15MHz_QPSK_37825_1RB#0_30~1000_30~1000	Band38_15MHz_QPSK_37825_1RB#0_1000~20000_1000~20000
	/
Band38_15MHz_QPSK_37825_1RB#0_20000~27000_20000~27000	/
/	
/	Band38_15MHz_16QAM_37825_1RB#0_30~1000_30~1000





Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

	
Band38_15MHz_16QAM_37825_1RB#0_1000~20000_1000~20000	Band38_15MHz_16QAM_37825_1RB#0_20000~27000_20000~27000
	
Band38_15MHz_QPSK_37825_1RB#74_30~1000_30~1000	Band38_15MHz_QPSK_37825_1RB#74_1000~20000_1000~20000
	/
Band38_15MHz_QPSK_37825_1RB#74_20000~27000_20000~27000	/




Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.






	/
Band38_15MHz_QPSK_37825_75RB#0_20000~27000_20000~27000	/
/	
/	Band38_15MHz_16QAM_37825_75RB#0_30~1000_30~1000
	
Band38_15MHz_16QAM_37825_75RB#0_1000~20000_1000~20000	Band38_15MHz_16QAM_37825_75RB#0_20000~27000_20000~27000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.


	
Band38_15MHz_QPSK_38000_1RB#0_30~1000_30~1000	Band38_15MHz_QPSK_38000_1RB#0_1000~20000_1000~20000
	/
Band38_15MHz_QPSK_38000_1RB#0_20000~27000_20000~27000	/
/	
/	Band38_15MHz_16QAM_38000_1RB#0_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.

Attestation of Global Compliance(Shenzhen)Co., Ltd
Attestation of Global Compliance(Shenzhen)Std & Tech Co., Ltd
Tel: +86-755 2523 4088 E-mail: agc@agccert.com Web: <http://www.agccert.com/>

	
Band38_15MHz_16QAM_38000_1RB#0_1000~20000_1000~20000	Band38_15MHz_16QAM_38000_1RB#0_20000~27000_20000~27000
	
Band38_15MHz_QPSK_38000_1RB#74_30~1000_30~1000	Band38_15MHz_QPSK_38000_1RB#74_1000~20000_1000~20000
	/
Band38_15MHz_QPSK_38000_1RB#74_20000~27000_20000~27000	/

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the “Dedicated Testing/Inspection Stamp” is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.