

13 Laetitia Lane  
Landenberg, PA 19350-1051

(610) 255-5678 Phone  
(866) 822-0010 Fax  
krosenzweig@tracexinc.com

March 8, 2022

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

RE: No FCC ID on Module Label Request Letter

The module (FCC ID: 2A3UI-TX4871) is too small (9.0 x 11.5 mm) to put the FCC ID on the module. We will be applying the FCC ID on the shipping package and in the user guide instead of the module.

The user guide/OEM installation manual will provide detailed instructions for the Host manufacturer how to label the final host device correctly. Here is the labelling instructions for the host device:

Contains FCC ID: 2A3UI-TX4871

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference, and
- (2) This device must accept any interference received, including interference that may cause undesired operation.

Please see the label location exhibit in the filing to see the location of the FCC ID on the product packaging.

Sincerely

  
Kenneth S. Rosenzweig  
CEO, TraceX, Inc.