





Band26-3MHz-16QAM-26705-1RB#0

Band26-3MHz-16QAM-26705-15RB#0





Band26-3MHz-16QAM-26805-1RB#0

Band26-3MHz-16QAM-26805-15RB#0





Band26-3MHz-16QAM-27025-1RB#14

Band26-3MHz-16QAM-27025-15RB#0





Band26-5MHz-QPSK-26715-1RB#0

Band26-5MHz-QPSK-26715-25RB#0





Band26-5MHz-QPSK-26815-1RB#0

Band26-5MHz-QPSK-26815-25RB#0





Band26-5MHz-QPSK-27015-1RB#24

Band26-5MHz-QPSK-27015-25RB#0





Band26-5MHz-16QAM-26715-1RB#0

Band26-5MHz-16QAM-26715-25RB#0





Band26-5MHz-16QAM-26815-1RB#0

Band26-5MHz-16QAM-26815-25RB#0





Band26-5MHz-16QAM-27015-1RB#24

Band26-5MHz-16QAM-27015-25RB#0





Band26-10MHz-QPSK-26740-1RB#0

Band26-10MHz-QPSK-26740-1RB#49



Band26-10MHz-QPSK-26740-50RB#0


Band26-10MHz-QPSK-26840-1RB#0



Band26-10MHz-QPSK-26840-50RB#0



Band26-10MHz-16QAM-26740-1RB#0






Band26-10MHz-16QAM-26740-1RB#49

Band26-10MHz-16QAM-26740-50RB#0




Band26-10MHz-16QAM-26840-1RB#0

Band26-10MHz-16QAM-26840-50RB#0




Band26-15MHz-QPSK-26865-1RB#0

Band26-15MHz-QPSK-26865-75RB#0




11:35:03 02.08.2022

Band26-15MHz-16QAM-26865-1RB#0




11:35:52 02.08.2022

Band26-15MHz-16QAM-26865-75RB#0



11:35:27 02.08.2022



11:36:15 02.08.2022


Band38-5MHz-QPSK-37775-1RB#0

Band38-5MHz-QPSK-37775-25RB#0




16:35:53 28.07.2022

Band38-5MHz-QPSK-38225-1RB#24




16:46:57 28.07.2022

Band38-5MHz-QPSK-38225-25RB#0




16:58:03 28.07.2022




17:09:04 28.07.2022

Band38-5MHz-16QAM-37775-1RB#0

Band38-5MHz-16QAM-37775-25RB#0




16:41:24 28.07.2022




16:52:27 28.07.2022

Band38-5MHz-16QAM-38225-1RB#24

Band38-5MHz-16QAM-38225-25RB#0




17:03:34 28.07.2022




17:14:34 28.07.2022

Band38-10MHz-QPSK-37800-1RB#0


Band38-10MHz-QPSK-37800-50RB#0




Band38-10MHz-QPSK-38200-1RB#49




Band38-10MHz-QPSK-38200-50RB#0




Band38-10MHz-16QAM-37800-1RB#0



Band38-10MHz-16QAM-37800-50RB#0





Band38-10MHz-16QAM-38200-1RB#49




Band38-10MHz-16QAM-38200-50RB#0







Band38-15MHz-QPSK-37825-1RB#0

Band38-15MHz-QPSK-37825-75RB#0




Band38-15MHz-QPSK-38175-1RB#74

Band38-15MHz-QPSK-38175-75RB#0



Band38-15MHz-16QAM-37825-1RB#0

Band38-15MHz-16QAM-37825-75RB#0




17:25:52 28.07.2022

Band38-15MHz-16QAM-38175-1RB#74




10:33:43 29.07.2022

Band38-15MHz-16QAM-38175-75RB#0




17:46:30 28.07.2022

Band38-20MHz-QPSK-37850-1RB#0




10:44:16 29.07.2022

Band38-20MHz-QPSK-37850-100RB#0




10:50:03 29.07.2022

Band38-20MHz-QPSK-38150-1RB#99



11:00:18 29.07.2022

Band38-20MHz-QPSK-38150-100RB#0




11:10:31 29.07.2022

Band38-20MHz-16QAM-37850-1RB#0




11:20:43 29.07.2022

Band38-20MHz-16QAM-37850-100RB#0




10:55:14 29.07.2022

Band38-20MHz-16QAM-38150-1RB#99




11:04:55 29.07.2022

Band38-20MHz-16QAM-38150-100RB#0





11:15:16 29.07.2022

Band41-5MHz-QPSK-39675-1RB#0





11:26:13 29.07.2022

Band41-5MHz-QPSK-39675-25RB#0





Band41-5MHz-QPSK-41565-1RB#24

Band41-5MHz-QPSK-41565-25RB#0



Band41-5MHz-16QAM-39675-1RB#0

Band41-5MHz-16QAM-39675-25RB#0



Band41-5MHz-16QAM-41565-1RB#24

Band41-5MHz-16QAM-41565-25RB#0