



Please refer to following plots:

Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:18:20

Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:18:30

Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:18:42

Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:18:52

Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:19:08

Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:19:18

Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:25:46

Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:25:56

Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:26:09

Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:26:19

Band 2\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:26:31

Band 2\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:26:41

Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:27:48

Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:27:58

Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 17.MAY.2023 22:28:14


Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 17.MAY.2023 22:28:24




Band 2\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:28:40

Band 2\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:28:50

Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:30:50

Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:31:00

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:31:13

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:31:23

Band 2\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:31:35

Band 2\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:31:45

Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:32:57

Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:33:07

Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:33:23

Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:33:33

Band 2\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:33:46

Band 2\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:33:56

Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 17.MAY.2023 22:36:06


Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 17.MAY.2023 22:36:16




Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:36:29

Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:36:39

Band 2\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:36:56

Band 2\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:37:06

Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:37:21

Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:37:31

Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:37:46

Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:37:56

Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:38:09

Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:38:18

Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:49:13

Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:49:23

Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:49:39

Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:49:49

Band 4\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 17.MAY.2023 22:50:04


Band 4\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 17.MAY.2023 22:50:17




Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:55:23

Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:55:33

Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:55:45

Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:55:55

Band 4\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:56:08

Band 4\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:56:18

Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:59:33

Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 22:59:43

Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 22:59:55

Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:00:05

Band 4\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:00:18

Band 4\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:00:28

Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:01:52

Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:02:02

Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 17.MAY.2023 23:02:19


Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)



Date: 17.MAY.2023 23:02:29




Band 4\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:02:42

Band 4\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:02:52

Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:04:36

Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:04:46

Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:05:02

Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:05:12

Band 4\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:05:25

Band 4\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:05:35

Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:05:50

Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:06:00

Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:06:13

Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:06:23

Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:06:35

Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:06:45

Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 17.MAY.2023 23:07:21


Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 17.MAY.2023 23:07:31




Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:07:46

Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:07:56

Band 66\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:08:08

Band 66\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:08:18

Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:09:02

Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:09:12

Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:09:24

Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:09:34

Band 66\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:09:46

Band 66\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:09:56

Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:10:34

Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:10:44

Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:10:57

Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:11:07

Band 66\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 17.MAY.2023 23:11:23


Band 66\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)



Date: 17.MAY.2023 23:11:32




Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:12:02

Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:12:12

Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:12:28

Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:12:38

Band 66\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:12:51

Band 66\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:13:01

Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:15:26

Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:15:36

Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:15:50

Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:16:00

Band 66\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:16:13

Band 66\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAY.2023 23:16:26

### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 21:54:45

### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 21:54:55

Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)



Date: 16.MAY.2023 21:55:07


Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)



Date: 16.MAY.2023 21:55:17




Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 21:55:33

Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 21:55:43

Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 21:56:50

Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 21:57:00

Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 21:57:12

Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 21:57:22

Band 5\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 21:57:38

Band 5\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 21:57:48

Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:00:01

Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:00:11

Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:00:24

Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:00:34

Band 5\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:00:46

Band 5\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:00:56

Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 16.MAY.2023 22:02:15


Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 16.MAY.2023 22:02:25




Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:02:38

Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:02:48

Band 5\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:03:01

Band 5\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:03:11

Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:03:30

Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:03:40

Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:03:52

Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:04:02

Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:04:15

Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:04:25

Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:07:06

Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:07:16

Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:07:32

Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:07:42

Band 12\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 16.MAY.2023 22:07:57


Band 12\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 16.MAY.2023 22:08:07




Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:09:14

Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:09:24

Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:09:39

Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:09:49

Band 12\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:10:02

Band 12\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:10:12

Band 12\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:11:12

Band 12\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:11:22

Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:11:34

Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:11:44

Band 12\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:12:00

Band 12\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:12:10

Band 13\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:12:26

Band 13\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:12:36

Band 13\_5 MHz\_Low\_QPSK\_RB25#0\_3(763MHz-775MHz)



Date: 17.MAY.2023 23:44:14


Band 13\_5 MHz\_Low\_QPSK\_RB25#0\_4(793MHz-806MHz)



Date: 16.MAY.2023 22:13:05




Band 13\_5 MHz\_Low\_QPSK\_RB25#0\_5(1.559GHz-1.61GHz)




Date: 16.MAY.2023 22:13:15

Band 13\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:13:27

Band 13\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:13:37

Band 13\_5 MHz\_Middle\_QPSK\_RB25#0\_3(763MHz-775MHz)




Date: 16.MAY.2023 22:13:50

Band 13\_5 MHz\_Middle\_QPSK\_RB25#0\_4(793MHz-806MHz)




Date: 16.MAY.2023 22:14:03

Band 13\_5 MHz\_Middle\_QPSK\_RB25#0\_5(1.5590GHz-1.61GHz)




Date: 16.MAY.2023 22:14:16

Band 13\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:14:28

Band 13\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:14:38

Band 13\_5 MHz\_High\_QPSK\_RB25#0\_3(763MHz-775MHz)




Date: 16.MAY.2023 22:14:51

Band 13\_5 MHz\_High\_QPSK\_RB25#0\_4(793MHz-806MHz)




Date: 16.MAY.2023 22:15:04

Band 13\_5 MHz\_High\_QPSK\_RB25#0\_5(1.5590GHz-1.61GHz)




Date: 16.MAY.2023 22:15:14

Band 13\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:16:31

Band 13\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:16:41

Band 13\_10 MHz\_Middle\_QPSK\_RB50#0\_3(763MHz-775MHz)




Date: 16.MAY.2023 22:16:54

Band 13\_10 MHz\_Middle\_QPSK\_RB50#0\_4(793MHz-806MHz)



Date: 16.MAY.2023 22:17:07


Band 13\_10 MHz\_Middle\_QPSK\_RB50#0\_5(1.559GHz-1.61GHz)



Date: 16.MAY.2023 22:17:17




Band 14\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:17:32

Band 14\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:17:42

Band 14\_5 MHz\_Low\_QPSK\_RB25#0\_3(763MHz-775MHz)




Date: 29.MAY.2023 23:00:40

Band 14\_5 MHz\_Low\_QPSK\_RB25#0\_4(799MHz-806MHz)




Date: 29.MAY.2023 23:05:16

Band 14\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:17:58

Band 14\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:18:08

Band 14\_5 MHz\_Middle\_QPSK\_RB25#0\_3(763MHz-775MHz)




Date: 29.MAY.2023 23:01:42

Band 14\_5 MHz\_Middle\_QPSK\_RB25#0\_4(799MHz-806MHz)




Date: 29.MAY.2023 23:06:59

Band 14\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:18:20

Band 14\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:18:30

Band 14\_5 MHz\_High\_QPSK\_RB25#0\_3(763MHz-775MHz)




Date: 29.MAY.2023 23:02:53

Band 14\_5 MHz\_High\_QPSK\_RB25#0\_4(799MHz-806MHz)




Date: 29.MAY.2023 23:07:37

Band 14\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:19:39

Band 14\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:19:49

Band 14\_10 MHz\_Middle\_QPSK\_RB50#0\_3(763MHz-775MHz)



Date: 29.MAY.2023 23:03:36


Band 14\_10 MHz\_Middle\_QPSK\_RB50#0\_4(799MHz-806MHz)



Date: 29.MAY.2023 23:08:57




Band 71\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:20:08

Band 71\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:20:18

Band 71\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:20:30

Band 71\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:20:40

Band 71\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:20:53

Band 71\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:21:03

Band 71\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:22:24

Band 71\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:22:34

Band 71\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:22:50

Band 71\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:23:00

Band 71\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:23:16

Band 71\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:23:26

Band 71\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:24:53

Band 71\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:25:03

Band 71\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 16.MAY.2023 22:25:16


Band 71\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-10GHz)



Date: 16.MAY.2023 22:25:26




Band 71\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:25:40

Band 71\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:25:50

Band 71\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAY.2023 23:39:59

Band 71\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:27:07

Band 71\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 16.MAY.2023 22:27:24

Band 71\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-10GHz)




Date: 16.MAY.2023 22:27:34

Band 71\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 16.MAY.2023 22:27:47

Band 71\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-10GHz)



Date: 16.MAY.2023 22:27:57