


9. SETUP PHOTOS

RF CONDUCTED MEASUREMENT SETUP



FREQUENCY STABILITY MEASUREMENT SETUP

INSIDE TEMP. CHAMBER PHOTO




OUTSIDE TEMP. CHAMBER PHOTO




RF RADIATED MEASUREMENT SETUP, 9 kHz - 30 MHz

FRONT PHOTO




BACK PHOTO




RF RADIATED MEASUREMENT SETUP, 30 - 1000 MHz

FRONT PHOTO



BACK PHOTO



END OF REPORT