



10/26/2022

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

To Whom It May Concern:


This letter is to inform you that we, Babson Diagnostics, Inc., are requesting Change in FCC ID for the new certification(s), FCC ID: 2A83TWFASPD. The device to be certified is identical in design and construction to the originally approved product(s).

In order to ensure continued compliance of the product, we have employed the following:

The product is still manufactured by the same company using the same design specifications as the original.

The same PCB design, layouts and parts list will be used to manufacture the product.

Sincerely,

DocuSigned by:

435943D0D28040C...

Eric Olson
Chief Operating Officer
Babson Diagnostics, Inc.
1205 Sheldon Cove, Suite 2-J
Austin, TX 78753
862-251-0705