




Band 2_1.4 MHz_Low_QPSK_RB6#0




Band 2_1.4 MHz_Middle_QPSK_RB6#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 19:33:50

Band 2_1.4 MHz_Middle_16QAM_RB6#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 19:34:08




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:34:23




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:34:37




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:51:20





ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:51:34






ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:51:48




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:52:01









ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:53:41




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:53:54




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:54:11



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:54:25




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:56:22



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:56:38


Band 2_10 MHz_Middle_QPSK_RB50#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 19:56:53

Band 2_10 MHz_Middle_16QAM_RB50#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 19:57:09




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:57:23




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:57:37




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 19:59:51



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:00:11




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:00:28



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:00:44


Band 2_15 MHz_High_QPSK_RB75#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai

Date: 9.AUG.2024 20:01:02


Band 2_15 MHz_High_16QAM_RB75#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai

Date: 9.AUG.2024 20:01:22


Band 2_20 MHz_Low_QPSK_RB100#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai

Date: 9.AUG.2024 20:05:51


Band 2_20 MHz_Low_16QAM_RB100#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai

Date: 9.AUG.2024 20:06:04


Band 2_20 MHz_Middle_QPSK_RB100#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 20:06:22

Band 2_20 MHz_Middle_16QAM_RB100#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 20:06:38




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:06:56




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:07:09




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:08:00




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:08:13




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:08:27




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:08:41







ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:09:49




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:10:02




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:10:17




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:10:30




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:10:44




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:11:00




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:11:43




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:12:00




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:12:14




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:12:28




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:12:45




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:12:58




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:13:42




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:13:58




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:14:12




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:14:29




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:14:43



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:15:00




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:24:46



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:24:59


Band 4_15 MHz_Middle_QPSK_RB75#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 20:25:14

Band 4_15 MHz_Middle_16QAM_RB75#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai



Date: 9.AUG.2024 20:25:27




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:25:41



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:25:55




Band 4_20 MHz_Middle_QPSK_RB100#0






ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:27:06

Band 4_20 MHz_Middle_16QAM_RB100#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:27:19






ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:28:59



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:29:15


Band 5_1.4 MHz_Middle_QPSK_RB6#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 20:29:36

Band 5_1.4 MHz_Middle_16QAM_RB6#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 20:29:55




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:30:13



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:30:29




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:36:39



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:36:56


Band 5_3 MHz_Middle_QPSK_RB15#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 20:37:13

Band 5_3 MHz_Middle_16QAM_RB15#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai



Date: 9.AUG.2024 20:37:27




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:37:41




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:37:54







ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:39:11




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:39:28




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:39:48



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:40:04




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:41:55



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:42:12


Band 5_10 MHz_Middle_QPSK_RB50#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 20:42:32

Band 5_10 MHz_Middle_16QAM_RB50#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 20:42:48




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:43:06



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:43:19




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:50:34




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:50:47

Band 12_1.4 MHz_Middle_QPSK_RB6#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:51:01


Band 12_1.4 MHz_Middle_16QAM_RB6#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:51:17




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:51:32




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:51:45




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:52:33




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:52:50




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:53:04




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:53:17




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:53:31



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:53:45




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:55:11




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:55:30

Band 12_5 MHz_Middle_QPSK_RB25#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:55:54


Band 12_5 MHz_Middle_16QAM_RB25#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:56:10




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:56:28




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:56:46




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:58:47




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:59:03




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:59:21





ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:59:37




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 20:59:51




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:00:05







ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:18:02




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:18:19




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:18:37



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:18:54




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:19:59




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:20:16

Band 17_10 MHz_Middle_QPSK_RB50#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:20:31

Band 17_10 MHz_Middle_16QAM_RB50#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:20:48


Band 17_10 MHz_High_QPSK_RB50#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai



Date: 9.AUG.2024 21:21:03

Band 17_10 MHz_High_16QAM_RB50#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai

Date: 9.AUG.2024 21:21:17




Band 25_1.4 MHz_Middle_QPSK_RB6#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:22:03


Band 25_1.4 MHz_Middle_16QAM_RB6#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:22:16




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:22:34





ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:22:51




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:23:44




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:23:58







ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:24:46





ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:25:00




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:25:57




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:26:14





ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:26:57




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:27:14




Date: 9.AUG.2024 21:28:28




Date: 9.AUG.2024 21:28:43




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:28:57



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:29:12



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:29:30



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:29:47




Date: 9.AUG.2024 21:34:32




Date: 9.AUG.2024 21:34:49

Band 25_15 MHz_Middle_QPSK_RB75#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:35:09


Band 25_15 MHz_Middle_16QAM_RB75#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:35:25




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:35:45





ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:36:01




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:37:22




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:37:39







ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:38:32



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:38:51




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:39:09




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:39:23

Band 66_1.4 MHz_Middle_QPSK_RB6#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:39:37


Band 66_1.4 MHz_Middle_16QAM_RB6#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:39:51




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:40:05




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:40:22




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:41:15




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:41:29




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:41:43




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:41:57




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:42:11



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:42:28




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:43:21




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:43:38

Band 66_5 MHz_Middle_QPSK_RB25#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:43:56


Band 66_5 MHz_Middle_16QAM_RB25#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:44:13




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:44:28




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:44:42




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:45:47




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:46:04




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:46:19





ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:46:36



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:46:54



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:47:11







Date: 9.AUG.2024 21:48:43




Date: 9.AUG.2024 21:49:02




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:49:19



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:49:35




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:50:42




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:50:58

Band 66_20 MHz_Middle_QPSK_RB100#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:51:18


Band 66_20 MHz_Middle_16QAM_RB100#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:51:34



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:51:51




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 21:52:11




Date: 9.AUG.2024 23:34:12




Date: 9.AUG.2024 23:34:28




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:34:45





ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:35:01




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:36:05



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:36:21




Band 7_10 MHz_High_QPSK_RB50#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 23:37:05

Band 7_10 MHz_High_16QAM_RB50#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai



Date: 9.AUG.2024 23:37:21




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:38:25




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:38:38







ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:39:22



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:39:35




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:40:36




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:40:53

Band 7_20 MHz_Middle_QPSK_RB100#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:41:09

Band 7_20 MHz_Middle_16QAM_RB100#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:41:23


Band 7_20 MHz_High_QPSK_RB100#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 23:41:36

Band 7_20 MHz_High_16QAM_RB100#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.AUG.2024 23:41:50




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 12:27:27




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 12:27:43




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 12:28:00




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 12:28:16




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 12:28:33




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 12:28:49




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 12:29:54




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 12:30:10




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:58:20




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:58:39




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:58:56




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:59:12




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:59:26




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.AUG.2024 23:59:42




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:01:27




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:01:43




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:02:00




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:02:17




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:04:10




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:04:26




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:04:43




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:04:59




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:05:16



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:05:32




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:07:44




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:08:01

Band 38_20 MHz_High_QPSK_RB100#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:08:18

Band 38_20 MHz_High_16QAM_RB100#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 10.AUG.2024 00:08:31

Band 41_5 MHz_Low_QPSK_RB25#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:05:23

Band 41_5 MHz_Low_16QAM_RB25#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:06:17


Band 41_5 MHz_Middle_QPSK_RB25#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai

Date: 9.SEP.2024 14:07:59


Band 41_5 MHz_Middle_16QAM_RB25#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 9.SEP.2024 14:08:48

Band 41_5 MHz_High_QPSK_RB25#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:10:06

Band 41_5 MHz_High_16QAM_RB25#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:11:45

Band 41_10 MHz_Low_QPSK_RB50#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:31:32

Band 41_10 MHz_Low_16QAM_RB50#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:30:29

Band 41_10 MHz_Middle_QPSK_RB50#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:32:53

Band 41_10 MHz_Middle_16QAM_RB50#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:34:02

Band 41_10 MHz_High_QPSK_RB50#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:35:14

Band 41_10 MHz_High_16QAM_RB50#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:35:58

Band 41_15 MHz_Low_QPSK_RB75#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:39:12

Band 41_15 MHz_Low_16QAM_RB75#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:40:07

Band 41_15 MHz_Middle_QPSK_RB75#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:41:34

Band 41_15 MHz_Middle_16QAM_RB75#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:42:30

Band 41_15 MHz_High_QPSK_RB75#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:43:32

Band 41_15 MHz_High_16QAM_RB75#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:44:17

Band 41_20 MHz_Low_QPSK_RB100#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:47:19

Band 41_20 MHz_Low_16QAM_RB100#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:48:51

Band 41_20 MHz_Middle_QPSK_RB100#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:50:01

Band 41_20 MHz_Middle_16QAM_RB100#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 9.SEP.2024 14:51:43


Band 41_20 MHz_High_QPSK_RB100#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai

Date: 9.SEP.2024 14:57:01



Band 41_20 MHz_High_16QAM_RB100#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai

Date: 9.SEP.2024 14:55:54

Band 26_1.4 MHz_Low_QPSK_RB6#0




Band 26_1.4 MHz_Middle_QPSK_RB6#0






ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:16:28

Band 26_1.4 MHz_Middle_16QAM_RB6#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:16:44






ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:18:01




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:18:17

Band 26_3 MHz_Middle_QPSK_RB15#0






ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:18:31

Band 26_3 MHz_Middle_16QAM_RB15#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:18:44







ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:20:01



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:20:17




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:20:34



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:20:50


Band 26_5 MHz_High_QPSK_RB25#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai


Date: 11.AUG.2024 18:21:16

Band 26_5 MHz_High_16QAM_RB25#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai

Date: 11.AUG.2024 18:21:32




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:22:19




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:22:35

Band 26_10 MHz_Middle_QPSK_RB50#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:22:49


Band 26_10 MHz_Middle_16QAM_RB50#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:23:02




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:23:18



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:23:34




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:24:29




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:24:42

Band 26_15 MHz_Middle_QPSK_RB75#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:24:56


Band 26_15 MHz_Middle_16QAM_RB75#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:25:09




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:25:26




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:25:39


814-824 MHz




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:46:23




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:46:39




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:47:25




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:47:41




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 19:11:24




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 19:11:40




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:47:56




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:48:09




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:48:49




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:49:02




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 19:12:57




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 19:13:10




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:49:26




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:49:42




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:50:35




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:50:54




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 19:14:37




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 19:14:53




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:51:15



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 18:51:28




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 19:16:13




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 19:16:26

Band 26_15 MHz_Low_QPSK_RB75#0




ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 3.SEP.2024 10:13:44


Band 26_15 MHz_Low_16QAM_RB75#0



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 3.SEP.2024 10:15:08



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 19:17:53



ProjectNo.:2401V31893E-RF Tester:Allen Bai
Date: 11.AUG.2024 19:18:12