

SENA MEXICO,S.A.DE C.V
Address: CARRETERA MÉXICO-TOLUCA No. 5324
INT. PLANTA BAJA, COL. EL YAQUI,CUAJIMALPA DE MORELOS
CIUDAD DE MÉXICO , Mexico
Tel.: +1-949-394-1881
E-mail: rfregoso@senwamobile.com

Date: 2020-06-15

FEDERAL COMMUNICATIONS COMMISSIONS
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

Attestation letter

Dear Sir or Madam,

The RF chip, model: SC9832E installed in our product Mobile Phone; Model number: LS5018F, FCC ID: 2AAA6-LS5018F, which supports WCDMA and LTE function. For use in the US market, this chip only support WCDMA band 2/5 and LTE band 2/4/7/66, the other WCDMA and LTE bands was disabled by the manufacturer in the software. The end user has no capability to activate it.

Sincerely,



Signature

Roberto Fregoso

CTO