Relay2, Inc.

1525 McCarthy Blvd. Suite 209, Milpitas, California 95035 United States

Date: 18 July 2021

Federal Communications Commission Authorization and Evaluation Division 1435 Oakland Mills Road Columbia, MD 21046

Subject: Request for a Change in Identification per Section §2.933 of the FCC Rules

Reference: FCC ID: 2AAA9-RA620

This change in identification request applies for a new FCC ID as established in 47 CFR 2.933(b) for a currently approved device.

This application by *Relay2, Inc.* will establish a new FCC ID under *Relay2, Inc.* grantee code for the purpose of marketing.

The original grant to Amigo Technology Inc. with FCC ID: RC6-APL5XX

will remain in effect.

An authorization letter by Amigo Technology Inc. is attached.

Per 2.933(b)

- 1.) The original identification is: FCC ID: RC6-APL5XX
- 2.) The original granted date is: 07/01/2021
- 3.) The equipment is electrically identical.
- 4.) The original test results are applicable and representative of this changed device
- 5.) External photographs incl. FCC ID label location info are included in this application.

The following files are electronically submitted as attachments:

- Cover Letter
- External Photos
- ID Lable and Location Info

Sincerely,

Lucas Chin Signatory

Lucas Chen, Sr. Hardware PM Director

lucas.chen@relav2.com

Relay2, Inc.