

Report No. : EED32K00204201 Page 81 of 102

### USB Power cable line 1: BLJ



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Report No. : EED32K00204201 Page 82 of 102



Radiated spurious emission Test Setup-3(Below 30MHz)



**Conducted Emissions Test Setup** 














Report No. : EED32K00204201 Page 83 of 102

### USB Power cable line 2: CS



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)

















Radiated spurious emission Test Setup-3(Below 30MHz)



**Conducted Emissions Test Setup** 













Report No.: EED32K00204201 Page 85 of 102

# **PHOTOGRAPHS OF EUT Constructional Details**

Test model No.:DXR-8



View of Product-1





















View of Product-3























View of Product-6


















View of Product-7



View of Product-8


















View of Product-9



View of Product-10














Report No. : EED32K00204201 Page 90 of 102



View of Product-11



View of Product-12

















View of Product-13



View of Product-14













Report No. : EED32K00204201 Page 92 of 102



View of Product-15



View of Product-16















Report No. : EED32K00204201 Page 93 of 102



View of Product-17



View of Product-18














Report No. : EED32K00204201 Page 94 of 102



View of Product-19



View of Product-20















Report No. : EED32K00204201 Page 95 of 102



View of Product-21



View of Product-22
















Report No. : EED32K00204201 Page 96 of 102



View of Product-23





View of Product-24













Report No. : EED32K00204201 Page 97 of 102



View of Product-25



View of Product-26













Report No. : EED32K00204201 Page 98 of 102



View of Product-27



View of Product-28















Report No. : EED32K00204201 Page 99 of 102



View of Product-29



View of Product-30













Report No.: EED32K00204201 Page 100 of 102

#### CS3B050055FU



View of Product-31



View of Product-32













Report No.: EED32K00204201 Page 101 of 102



View of Product-33



View of Product-34















Report No.: EED32K00204201 Page 102 of 102



View of Product-35



View of Product-36

## \*\*\* End of Report \*\*\*

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

Hotline: 400-6788-333 www.cti-cert.com E-mail: info@cti-cert.com Complaint call: 0755-33681700 Complaint E-mail: complaint@cti-cert.com