



**JOHN DEERE**

John Deere Electronic Solutions  
4101 19<sup>th</sup> Avenue North  
Fargo, ND 58102 U.S.A.

Date: October 16, 2013

TUV SUD BABT FCB  
Octagon House,  
Segensworth Road,  
Fareham,  
Hampshire,  
PO15 5RL

**Relevance of Test Reports**

RE: Deere & Company Model RE338096, FCC ID: 2AAFX-RE338096, IC: 11137A- RE338096

We, Deere & Company attest that the following Compliance Certification Services Inc Test Reports remain valid and applicable to Model RE338096 and they are representative of the compliance for this device.

Test Report Number	Date of Issue	Model Tested	Applicable Standards
SZ091014B02-RC	October 19, 2009	RS9110-N-11-02	RSS-210, Issue 7: June 2007
SZ091014B02-RP	October 19, 2009	RS9110-N-11-02	FCC Part 15.207, 15.209, 15.247

We also attest that Test Report SZ091014B02-RC has been reviewed and remains valid per the latest version of RSS-210, Issue 8: 2010.

Yours sincerely,

Company Officer: Orrin West  
Telephone Number: 701-552-8537  
Email: westorrib@johndeere.com