

**Randall Duval** 

IoT Engineering Manager Georgia-Pacific Consumer Products LP 1915 Marathon Ave Neenah, WI 54956 920-729-8428

Date: January 21, 2022

Subject: FCC ID: 2AALY-530GP / IC: 21620-530GP

## To Whom It May Concern:

• Per FCC 15.407(c), the device will automatically discontinue transmission in case of either absence of information to transmit or operational failure.

This is done via the device utilizing the 802.11 MAC protocol in its communication with othermodules. The 802.11 MAC provides for transmission only when information is present to transmit. When there is no information to transmit, no packets will be scheduled for transmissionand the RF transmit circuitry will remain off. In the case that operational failure is detected, themodule will be rebooted and transmission will cease until the processor verifies normal operation.

Thank you,

By: Randall Duval

Title: IoT Engineering Manager

On behalf of: Georgia-Pacific Consumer Products LP Telephone: 920-729-8428