





BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3684.99MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3684.99MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3684.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3684.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3684.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_3684.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3565.02MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3565.02MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM QPSK_3565.02MHz_Outer_Full_Ant1




n48_30kHz_SISO_NTNV_30MHz_CP-OFDM QPSK_3565.02MHz_Inner_Full_Ant1






n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3565.02MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3565.02MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3624.99MHz_Edge_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3624.99MHz_Edge_1RB_Right_Ant1






n48_30kHz_SISO_NTNV_30MHz_CP-OFDM QPSK_3624.99MHz_Outer_Full_Ant1




n48_30kHz_SISO_NTNV_30MHz_CP-OFDM QPSK_3624.99MHz_Inner_Full_Ant1






n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3624.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3624.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3684.99MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3684.99MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3684.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3684.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3684.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_3684.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3565.02MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3565.02MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3565.02MHz_Outer_Full_Ant1




n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3565.02MHz_Inner_Full_Ant1






n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3565.02MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3565.02MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3624.99MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3624.99MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3624.99MHz_Outer_Full_Ant1




n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3624.99MHz_Inner_Full_Ant1






n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3624.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3624.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3684.99MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3684.99MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3684.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3684.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3684.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_3684.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3565.02MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3565.02MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 64 QAM_3565.02MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 64 QAM_3565.02MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3565.02MHz_Inner_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3565.02MHz_Inner_1RB_Right_Ant1






n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3624.99MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3624.99MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3624.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3624.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3624.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3624.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3684.99MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3684.99MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3684.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3684.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3684.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_3684.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 256 QAM 3565.02MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 256 QAM 3565.02MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 256 QAM 3565.02MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 256 QAM 3565.02MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 256 QAM 3565.02MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 256 QAM 3565.02MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 256 QAM 3624.99MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 256 QAM 3624.99MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3624.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3624.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 256 QAM 3624.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 256 QAM 3624.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 256 QAM 3684.99MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM 256 QAM 3684.99MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3684.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3684.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3684.99MHz_Inner_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_3684.99MHz_Inner_1RB_Right_Ant1






1.2.4 30k_SISO_40MHz_NTNV

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM PI/2 BPSK_3570MHz_Edge_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM PI/2 BPSK_3570MHz_Edge_1RB_Right_Ant1






n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM PI/2 BPSK_3570MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM PI/2 BPSK_3570MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_PI/2_BPSK_3570MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_PI/2_BPSK_3570MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM PI/2 BPSK_3624.99MHz_Edge_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM PI/2 BPSK_3624.99MHz_Edge_1RB_Right_Ant1






n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM PI/2 BPSK_3624.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM PI/2 BPSK_3624.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_PI/2_BPSK_3624.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_PI/2_BPSK_3624.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_PI/2_BPSK_3679.98MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_PI/2_BPSK_3679.98MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM PI/2 BPSK_3679.98MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM PI/2 BPSK_3679.98MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_PI/2_BPSK_3679.98MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_PI/2_BPSK_3679.98MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3570MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3570MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3570MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM QPSK_3570MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3570MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3570MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3624.99MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3624.99MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3624.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3624.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3624.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3624.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_QPSK_3679.98MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3570MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3570MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3570MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3570MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3570MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3570MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3624.99MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3624.99MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3624.99MHz_Outer_Full_Ant1




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3624.99MHz_Inner_Full_Ant1






n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3624.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3624.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3679.98MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3679.98MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3679.98MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3679.98MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3679.98MHz_Inner_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3679.98MHz_Inner_1RB_Right_Ant1






n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3570MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3570MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3570MHz_Outer_Full_Ant1




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3570MHz_Inner_Full_Ant1






n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3570MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3570MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3679.98MHz_Edge_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3679.98MHz_Edge_1RB_Right_Ant1






n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3679.98MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3679.98MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3679.98MHz_Inner_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3679.98MHz_Inner_1RB_Right_Ant1






n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3570MHz_Edge_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3570MHz_Edge_1RB_Right_Ant1






n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3570MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3570MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3570MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3570MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Edge_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Edge_1RB_Right_Ant1






n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3679.98MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3679.98MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3679.98MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3679.98MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3679.98MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3679.98MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Edge_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Edge_1RB_Right_Ant1






n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3570MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3570MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Inner_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Inner_1RB_Right_Ant1






n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3624.99MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3624.99MHz_Edge_1RB_Right_Ant1






BUREAU
VERITAS


No.: PSU-NQN2412170317RF02

FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3624.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3624.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3624.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3624.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3679.98MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3679.98MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3679.98MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM QPSK_3679.98MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3679.98MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3679.98MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3570MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3570MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3570MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3570MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3570MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3570MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3624.99MHz_Edge_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3624.99MHz_Edge_1RB_Right_Ant1






n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3624.99MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3624.99MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3624.99MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3624.99MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3679.98MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3679.98MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3679.98MHz_Outer_Full_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3679.98MHz_Inner_Full_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3679.98MHz_Inner_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3679.98MHz_Inner_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3570MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3570MHz_Edge_1RB_Right_Ant1







BUREAU
VERITAS

No.: PSU-NQN2412170317RF02
FCC ID: 2AANY-ER815NRQ3

n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3570MHz_Outer_Full_Ant1




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3570MHz_Inner_Full_Ant1






n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3570MHz_Inner_1RB_Left_Ant1




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3570MHz_Inner_1RB_Right_Ant1





n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3624.99MHz_Edge_1RB_Left_Ant1



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3624.99MHz_Edge_1RB_Right_Ant1

