

EXHIBIT A - FCC ID LABELING AND LOCATION



FCC ID Label



MODEL NO. / MODÈLE NO.:
SML645BT

4060 E. Jurupa Street, Unit B,
Ontario CA 91761-1413, USA
www.singingmachine.com

MANUFACTURED IN CHINA FOR
FABRIQUÉ EN CHINE POUR
THE SINGING MACHINE CO., INC.



DC IN/Entrée en CC
POWER SOURCE
ALIMENTATION ÉLECTR.:
DC 12V =1.5A

CLASS 1 LASER PRODUCT
PRODUCTO LÁSER CLASE 1
PRODUIT LASER DE CLASSE 1
LASER-PRODUKT DER KLASSE 1

CAN ICES-3(B)/NMB-3(B)

FCC ID: 2AA0X-SML645BT
IC: 11387A-SML645BT

SERIAL NO. / NO. DE SÉRIE:
[Redacted box]

AUDIO PRODUCTS AND ACCESSORIES

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS:
(1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND
(2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRABLE OPERATION.

THIS PRODUCT COMPLIES WITH DHHS RULES 21 CFR SUBCHAPTER J APPLICABLE AT DATE OF MANUFACTURE.

CAUTION:

Use of controls or adjustments or performance of procedures other than those specified may result in hazardous radiation exposure.

DANGER:

INVISIBLE LASER RADIATION WHEN OPEN AND INTERLOCK FAILED OR DEFEATED, AVOID DIRECT EXPOSURE TO BEAM.

WARNING:

To reduce the risk of fire or electronic shock, do not expose this appliance to rain or moisture.



CAUTION
RISK OF ELECTRIC SHOCK
DO NOT OPEN



PRODUITS ET ACCESSOIRES AUDIO

CET APPAREIL EST CONFORME À LA SECTION 15 DES RÈGLEMENTS FCC. SON FONCTIONNEMENT EST SOUMIS AUX DEUX CONDITIONS SUIVANTES:
(1) CET APPAREIL NE DOIT PAS PROVOQUER D'INTERFÉRENCES NUISIBLES, ET
(2) CET APPAREIL DOIT ACCEPTER TOUTE INTERFÉRENCE, Y COMPRIS CELLES SUSCEPTIBLES DE PROVOQUER SON FONCTIONNEMENT INDÉSIRABLE.

CE PRODUIT EST CONFORME AUX RÈGLEMENTS 21 CFR SOUS-CHAPITRE J DE LA DHHS EN VIGUEUR À LA DATE DE FABRICATION.

ATTENTION:

Le fait d'utiliser, d'ajuster et de faire fonctionner l'appareil sans respecter les directives fournies dans la documentation qui l'accompagne risque d'entraîner une exposition dangereuse au rayonnement laser.

DANGER:

RAYONNEMENT LASER INVISIBLE LORSQUE LE LECTEUR EST OUVERT MAL VERROUILLÉ. ÉVITER TOUT CONTACT DIRECT AVEC LE FAISCEAU LUMINEUX.

AVERTISSEMENT:

Pour réduire le risque d'incendie ou d'électrocution, n'exposez pas cet appareil à la pluie ni à l'humidité excessive.



AVERTISSEMENT
RISQUE DE CHOC
ÉLECTRIQUE NE PAS OUVRIR



QINGYUAN WEILIBANG WOODING CO., LTD.
05/2017

The goods indicated on this shipment will be produced with medium density fiberboard. We hereby certify that these goods were produced in compliance with the applicable California emission standards specified in Section 93120.2(a) Phase 2 of the ATCM to Reduce Formaldehyde from Composite Wood Products.

Proposed FCC ID Label Location

Label Here



The label shown shall be permanently affixed at a conspicuous location on the device and be readily visible to the user at the time of purchase (Labeling requirements per 2.925)
