

**LEEDARSON LIGHTING CO., LTD.**

Xingda Road, Xingtai Industrial Zone, Changtai County, Zhangzhou, Fujian, China

2019-06-18

Federal Communications Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia, MD 21046

List of Differences for FCC ID: 2AB2QNS01RA13FR125

Location	Old PCB of FCC ID: 2AB2QNS01RA13FR125	New PCB of FCC ID: 2AB2QNS01RA13FR125
C10	NO	ADD (50V, 150PF)
R12	1/4W,240K $\Omega$	1/4W,82K $\Omega$
R13	1/8W,10K $\Omega$	1/8W,3.3K $\Omega$
R23	1/4W,0.91 $\Omega$	1/4W,0.82 $\Omega$

All component changes are intended to improve power performance and stability

These changes can cause test items Conducted emission and Field Strength of Spurious Emissions change

Sincerely,

**LEEDARSON LIGHTING CO., LTD.**



-----  
(Vick Zhang)  
(safety engineer)